

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/16/2023

Submitted Date:

11/20/2023

Document Number:

708902288

FIELD INSPECTION FORM

Loc ID: 322467 Inspector Name: Smelser, Wayne On-Site Inspection: 2A Doc Num: _____

Status Summary:

THIS IS A FOLLOW UP INSPECTION

FOLLOW UP INSPECTION REQUIRED

NO FOLLOW UP INSPECTION REQUIRED

Findings:

13 Number of Comments

1 Number of Corrective Actions

Corrective Action Response Requested

Operator Information:

OGCC Operator Number: 10550

Name of Operator: MUSTANG RESOURCES LLC

Address: PO BOX 13550

City: BAKERSFIELD State: CA Zip: 93389

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, Mustang		nwelch@vaqueroenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210880	WELL	SI	07/01/2023	GW	045-06638	MACKELY 34-12-6S-94W	SI

General Comment:

[CECMC Inspection Report Summary](#)

On 11/16/2023 at approximately 12:11 hours, I, Compliance Specialist, Wayne Smelser Conducted an on-site inspection at MUSTANG RESOURCES LLC MACKELY 34-12-6S-94W Location # 322467 in Garfield County Colorado. Location is within High Priority/Density/Black Bear Habitat areas/Bald Eagle Roost Site & in close proximity to NSO Habitat area. Location is approximately 234 yards from Spruce Creek & approximately 415 yards from the Colorado River. While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

1. Stormwater - Erosion & transport of sediment off location & lack of stabilization/compaction with a CA date of 12/05/2023

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.
This is a summary of inspection report.

Location

Lease Road:			
	Type Access		
comment:			
Corrective ActionL			Date:

Overall Good:

Signs/Marker:			
	Type WELLHEAD		
Comment:			
Corrective Action:			Date:
	Type BATTERY		
Comment:	No tank battery		
Corrective Action:			Date:

Emergency Contact Number:

Comment:	911/1-888-291-8588		
Corrective Action:			Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:			corrective date
Type: Deadman # & Marked	# 1		
Comment:	Marked		
Corrective Action:			Date:
Type: Plunger Lift	# 0		
Comment:	Well is not on plunger lift		
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	No form of pressure monitoring equipment located on bradenhead, bradenhead valve is accessible.		
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 210880 Type: WELL API Number: 045-06638 Status: SI Insp. Status: SI

Producing Well

Comment: [Producing, well is not on plunger lift](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel				Sparse
Compaction	Fail					Lack of stabilization/compaction
Other	Fail					Erosion & transport of sediment
		Compaction				
Gravel						Sparse to none in areas

Comment: [1. Lack of stabilization/compaction on location](#)
[2. Erosion & transport of sediment off location \(NE area of location\)](#)

Corrective Action: **Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. BMPs shall be maintained until the facility is abandoned and final reclamation is achieved.**

Date: 12/05/2023

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Please refer to Stormwater for observed compliance issues.	smelserw	11/20/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403602377	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6330113
708902289	Inspection 708902288 Stormwater photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6330110
708902290	Inspection 708902288 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6330111