

Location

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	Adequate		
Corrective Action:		Date:	

Good Housekeeping:			
Type	DEBRIS		
Comment:	Dead debris inside fence.		
Corrective Action:	Comply with Rule 606	Date:	11/27/2023

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	OTHER		
Comment:	Chainlink		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Cattle Fence		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Ancillary equipment	# 1		
Comment:	Automation RTU		
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 201584 Type: WELL API Number: 001-06987 Status: AC Insp. Status: AC**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary On (11/15/2023) at approximately (9:50am). I, Inspector Keith Huck, conducted an on-site inspection. Operator: Colorado Interstate Gas Location name: Totem#11 API # 001-06987 Location ID #: 319851 County: Adams While there, I observed a (AC) well. During this inspection the following possible compliance issues were observed: Debris inside fenced area Comply with Rule 606 CA Date: 11/27/2023 A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	huckk	11/20/2023

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403601406	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6329006
709700209	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6328947