

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/09/2023

Submitted Date:

11/20/2023

Document Number:

710500114

FIELD INSPECTION FORM

Loc ID 307609 Inspector Name: Sanchez, Chris On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10705
Name of Operator: EVERGREEN NATURAL RESOURCES LLC
Address: 1875 LAWRENCE ST STE 1150
City: DENVER State: CO Zip: 80202

Findings:

- 4 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Beardslee, Tom		tom.beardslee@state.co.us	
, ENR	719-846-7898	cogcc.evergreen@enrllc.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
217892	WELL	PR	08/01/2022	CBM	071-06671	TAD POLE 21-12	EI
307609	LOCATION	AC			-	TAD POLE-634S66W 12NENW	EI

General Comment:

This is an Environmental Inspection for the Tadpole 21-12 Facility 307609, Location located in Las Animas County Co.

Location

Lease Road:			
Type	Other		
comment:	Secondary Access Road between the Liger 12-12 reclamation location and the Tadpole 21-12 well location has sections of Erosion and Exposed Gathering Line.		
Corrective Action:	Comply with Rule 1002.f. and Rule 1102.e.	Date:	12/14/2023

Overall Good:

Emergency Contact Number:

Comment:	<input style="width: 95%;" type="text"/>		
Corrective Action:	<input style="width: 95%;" type="text"/>	Date:	_____

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:	<input style="width: 95%;" type="text"/>		
Corrective Action:		Date:	

Flaring:

Type			
Comment:	<input style="width: 95%;" type="text"/>		
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 217892 Type: WELL API Number: 071-06671 Status: PR Insp. Status: EIFacility ID: 307609 Type: LOCATION API Number: - Status: AC Insp. Status: EI**COGCC Comments**

Comment	User	Date
Secondary Access Road between the Liger 12-12 reclamation location and Tadpole 21-12 well location has sections of Erosion and Exposed Gathering Line. Comply with Rule 1002.f. and Rule 1102.e.	sanchezcc	11/13/2023

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403600814	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6328496
710500115	Location Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6328492