

Inspection Photos

Loc #: 484359

Operator: DESERT EAGLE OPERATING

Inspection Date: 11/21/2023

County: Las Animas



Inspection Photos



Photo 1. Facing east along the access road to the Red Rocks #35-08 drill site.



Inspection Photos



Photo 2. Facing southeast toward the Red Rocks #35-08 drill site. It appears soils have been graded however, soils are compacted from heavy equipment and will need to be properly decompacted.



Inspection Photos



Photo 3. Facing southeast toward the drill cuttings pile. The pile is not properly stored with containment. It appears the drill cuttings were used as berms and wattles are not maintained around the pile.



Inspection Photos



Photo 4. It appears the pile has been reduced in size since previous inspection. Photo on the left was taken 11/21 compared to the photo on the right taken 9/8/2023.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc #: 484359 | Date: 11/21/2023

Inspection Photos



Photo 5. Facing southeast toward the drill cuttings pile. The pile is not properly stored with containment. It appears the drill cuttings were used as berms and wattles are not maintained around the pile.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc #: 484359 | Date: 11/21/2023

Inspection Photos



Photo 6. The material used for a berm is the same color as the drill cuttings. The cuttings pile is not properly stored with sufficient containment..



Inspection Photos



Photo 7. It appears the area of the wellhead was excavated and subsoils were brought to the surface. The subsoils have the light colored rock material shown in the pile next to the excavator.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc #: 484359 | Date: 11/21/2023