

Inspection Photos

Location Name: VISION ENERGY LLC, SOUTH SHALE RIDGE-68S98W/14NENE

Location ID: 324270

Date: 11/22/2023



West End of Location – Photo #07602



Wellhead/Weeds – Photo #07603

Inspection Photos

Location Name: VISION ENERGY LLC, SOUTH SHALE RIDGE-68S98W/14NENE

Location ID: 324270

Date: 11/22/2023



Separator/Gas Meter/Weeds – Photo #07605



Tank Battery/Weeds – Photo #07604

Inspection Photos

Location Name: VISION ENERGY LLC, SOUTH SHALE RIDGE-68S98W/14NENE

Location ID: 324270

Date: 11/22/2023



Erosion Transporting Sediment Off Location – Photo #07614



Erosion Transporting Sediment Off Location – Photo #07612

Inspection Photos

Location Name: VISION ENERGY LLC, SOUTH SHALE RIDGE-68S98W/14NENE

Location ID: 324270

Date: 11/22/2023



Insufficient Waddle BMP – Photo #07613



Insufficient Waddle BMP – Photo #07615

Inspection Photos

Location Name: VISION ENERGY LLC, SOUTH SHALE RIDGE-68S98W/14NENE

Location ID: 324270

Date: 11/22/2023



**Erosion Transporting Sediment to Watershed – Photo
#07606**



**Erosion Transporting Sediment to Watershed – Photo
#07607**

Inspection Photos

Location Name: VISION ENERGY LLC, SOUTH SHALE RIDGE-68S98W/14NENE

Location ID: 324270

Date: 11/22/2023



Lack of Stabilization – Photo #07608



Lack of Stabilization – Photo #07609

Inspection Photos

Location Name: VISION ENERGY LLC, SOUTH SHALE RIDGE-68S98W/14NENE

Location ID: 324270

Date: 11/22/2023



Insufficient Vehicle Tracking BMPs at Location Entrance/Exit
– Photo #07610