

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/22/2023

Submitted Date:

11/27/2023

Document Number:

708301247

FIELD INSPECTION FORM

 Loc ID 312598 Inspector Name: Morris, Matthew On-Site Inspection 2A Doc Num: _____
Operator Information:OGCC Operator Number: 10770Name of Operator: VISION ENERGY LLCAddress: P O BOX 370City: IGNACIO State: CO Zip: 81137**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:11 Number of Comments7 Number of Corrective Actions

-
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**Contact Information:**

Contact Name	Phone	Email	Comment
ENERGY, VISION		mco@visionenergy.biz	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
221992	WELL	SI	04/01/2010	CBM	077-08594	SOUTH SHALE RIDGE 1-14	SI

General Comment:[COGCC Inspection Report Summary](#)

On 11/22/2023 at approximately 12:35, Compliance Inspector Matthew Morris conducted a follow-up inspection at VISION ENERGY LLC, SOUTH SHALE RIDGE-68S98W/14NENE at Location ID #312598 in Mesa County, Colorado.

Normal production operations were observed.

During the inspection, the following compliance issues were observed:

- 1) Weeds/undesirable plant species present throughout production area
- 2) Tank battery berm has inadequate permeability due to weed growth
- 3) Trash and debris on location which includes a fire pit and burned trash
- 4) Inaccurate operator information on battery sign and wellhead sign
- 5) Stormwater; refer to Stormwater section

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Wellhead sign has inaccurate operator information.		
Corrective Action:	Install wellhead sign with correct information to comply with Rule 605.d.	Date:	05/18/2023
Type	BATTERY		
Comment:	Battery sign has inaccurate operator information.		
Corrective Action:	Install battery sign with correct information to comply with Rule 605.h.	Date:	05/18/2023

Emergency Contact Number:

Comment:	911		
Corrective Action:		Date:	

Good Housekeeping:

Type	WEEDS		
Comment:	Weeds and undesirable plant species present throughout production area.		
Corrective Action:	Remove weeds and undesirable plant species to comply with Rule 606.	Date:	04/25/2023
Type	DEBRIS		
Comment:	Fire pit and other debris present on location.		
Corrective Action:	Remove debris from location to comply with Rule 606.	Date:	04/25/2023
Type	TRASH		
Comment:	Burned trash present on location.		
Corrective Action:	Remove trash from location to comply with Rule 606.	Date:	04/25/2023

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type			corrective date
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:					
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:
Paint					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Inadequate	Walls Insufficient	Base Insufficient	Inadequate	
Comment: Containment is not sufficiently impervious to contain spilled or released materials due to weed growth.					
Corrective Action: Repair berm and remove weeds to comply with Rule 603.o.					Date: 05/18/2023
Venting:					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
Flaring:					
Type					
Comment:					
Corrective Action:					Date:

Inspected Facilities

Facility ID: 221992 Type: WELL API Number: 077-08594 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action:

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Waddles						
Rip Rap						
Compaction						
		Ditches				
Berms						
		Compaction				
		Other	Fail			Insufficient erosion controls

Comment: 1) Rill erosion transporting sediment down access road
 2) Inadequate tracking BMP on lease road to/from location entrance

Corrective Action: Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to comply with Rule 1002.

Date: 09/22/2023

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708301248	Photo Log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6335450