

FORM
INSPRev
X/20

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/17/2023

Submitted Date:

11/28/2023

Document Number:

698601291

FIELD INSPECTION FORM

Loc ID 304615 Inspector Name: St John, William (Cal) On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10536
Name of Operator: SMITH ENERGY LLC
Address: 1540 MAIN ST SUITE 218 #334
City: WINDSOR State: CO Zip: 80550

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 14 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Smith, Chris	970-330-7034	smithenergy@live.com	
Smith, Glenn	970-330-7034	gsmithten@what-wire.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
268774	WELL	PR	09/12/2003	GW	125-08770	MONK 2-18	PR

General Comment:

[Routine Inspection.](#)

Location			
Lease Road:			
Type	Access		
comment:	Two track off maintained County Road. Active agricultural cropland with seasonal access.		
Corrective Action:		Date:	
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Well sign located inside well fencing. Sticker is peeling and needs to be replaced.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Well sign posted at remote Gas Meter Run. Sticker is peeling and needs to be replaced.		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	Emergency contact information posted on both the Well location and Meter Shed signs.		
Corrective Action:		Date:	
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	Steel post and tubing fencing.		
Corrective Action:		Date:	
Equipment:			
Type: Other	# 1		corrective date
Comment:	Separator Shed at remote Gas Meter Run.		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Meter Shed at remote Gas Meter Run.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Wellhead. Tubing in the wellbore. Tubing valve open. Casing valve closed.		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Bradenhead plumbed to surface.		
Corrective Action:		Date:	

Type: Gas Meter Run	# 1		
Comment:	Remote Gas Meter Run located on CR 51. Gas Meter Run. Chart in Meter Box dated 10-31-23. Meter Calibration/Test Log dated.7-28-22 . Well Inlet Valve open. Gas Outlet Valve open. Gas meter is overdue calibration.		
Corrective Action:	Calibrate gas metering equipment annually to comply with rule 430.d.(1).	Date:	12/29/2023
Type: Vertical Separator	# 1		
Comment:	Locxated at remote Gas Meter Run.		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 268774 Type: WELL API Number: 125-08770 Status: PR Insp. Status: PR

Producing Well

Comment: [Electronic Well File reflects last Production/Status reported 9/1/2023 and Well Status as PR. Based on current valve settings at time of inspection the well is PR.](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
698601324	Inspection photos.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6336306