

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/22/2023

Submitted Date:

11/28/2023

Document Number:

708301251**FIELD INSPECTION FORM**

Loc ID 323851	Inspector Name: Morris, Matthew	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input checked="" type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 9 Number of Comments 5 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE
Operator Information: OGCC Operator Number: <u>10770</u> Name of Operator: <u>VISION ENERGY LLC</u> Address: <u>P O BOX 370</u> City: <u>IGNACIO</u> State: <u>CO</u> Zip: <u>81137</u>				

Contact Information:			
Contact Name	Phone	Email	Comment
ENERGY, VISION		mco@visionenergy.biz	

Inspected Facilities:							
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210985	WELL	PR	03/01/2021	CBM	045-06743	SOUTH SHALE RIDGE 10-7	PR

General Comment: <p>COGCC Inspection Report Summary</p> <p>On 11/22/2023 at approximately 12:55, Compliance Inspector Matthew Morris conducted a follow-up inspection at VISION ENERGY LLC, SOUTH SHALE RIDGE-68S98W/7NWSE at Location ID #323851 in Garfield County, Colorado.</p> <p>Normal production operations were observed.</p> <p>During the inspection, the following compliance issues were observed:</p> <ol style="list-style-type: none"> 1) Weeds have encroached on all production equipment 2) Unused equipment stored on location 3) Inaccurate tank label on produced water tank 4) Antifreeze containers stored on location with no NFPA labels or secondary containment 5) Tank battery berm permeability inadequate due to weed growth/damage <p>A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.</p>
--

LocationOverall Good: ☐**Signs/Marker:**

Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass on the side of the unit indicates that the storage tank contains an unknown fluid. No form of labeling or markers is present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Inaccurate information (wrong operator) on tank label on produced water tank.		
Corrective Action:	Install accurate labels on tank to comply with Rule 605.	Date:	07/13/2023

Emergency Contact Number:

Comment: 911/(970) 858-8550

Corrective Action:

Date: _____

Good Housekeeping:

Type	STORAGE OF SUPL		
Comment:	Antifreeze stored on location (No NFPA label or secondary containment).		
Corrective Action:	Remove stored supplies from location to comply with Rule 606.	Date:	12/05/2023
Type	WEEDS		
Comment:	Weeds have encroached all production equipment on location.		
Corrective Action:	Remove weeds to comply with Rule 606.	Date:	03/21/2023
Type	STORAGE OF SUPL		
Comment:	Unused equipment stored on location.		
Corrective Action:	Remove unused equipment to comply with Rule 606.	Date:	06/02/2023

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Horizontal Heated Separator	# 1		corrective date
Comment:			
Corrective Action:		Date:	

Type: Gas Meter Run	# 1	
Comment:		
Corrective Action:		Date:
Type: Bird Protectors	# 1	
Comment:		
Corrective Action:		Date:
Type: Pump Jack	# 1	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient	Base Insufficient	Inadequate
Comment:	Berm permeability insufficient due to weed growth.			
Corrective Action:	Repair berm to comply with Rule 603.o.			
			Date:	04/14/2023

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities				
Facility ID: 210985	Type: WELL	API Number: 045-06743	Status: PR	Insp. Status: PR
Producing Well				
Comment:				
Corrective Action:				Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts				
		Ditches				
		Sediment Traps				
		Compaction				
		Gravel				
		Rip Rap				
Berms						
Gravel						
Compaction						
		Berms				

Comment: [Light gravel and compaction on location and lease road; future stormwater events may create tracking issues.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708301252	Photo Log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6337084