

Inspection Photos
Location Name: BM Federal #13-12
API: 05-081-07395



BM Federal #13-12 location photo.



BM Federal #13-12 well head and impacted area.

Inspection Photos
Location Name: BM Federal #13-12
API: 05-081-07395



Stained and damp soil. View to the northeast.



Stained and damp soil. View to the west/southwest.

Inspection Photos
Location Name: BM Federal #13-12
API: 05-081-07395



Close up of BM Federal #13-12 well head. All valves appeared to be in the closed position during this inspection.



Background soil sample location.

Inspection Photos
Location Name: BM Federal #13-12
API: 05-081-07395



Impacted soil sample location.



Soil sample taken beyond apparent terminus of flow path.

Inspection Photos
Location Name: BM Federal #13-12
API: 05-081-07395



Stained soil and vegetation. View to the northwest.



One inch valve is wet and stained.

Inspection Photos
Location Name: BM Federal #13-12
API: 05-081-07395



2 inch valve on the upper left of the well head dripped once every 10-15 seconds.



Drips from this valve could be seen once every 10-15 seconds.