

FORM  
INSPRev  
X/20State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/14/2023

Submitted Date:

11/29/2023

Document Number:

704900120

## FIELD INSPECTION FORM

 Loc ID 313360 Inspector Name: Hughes, Jim On-Site Inspection  2A Doc Num: \_\_\_\_\_
**Operator Information:**OGCC Operator Number: 10323Name of Operator: ENTEK GRB LLCAddress: 165 SOUTH UNION #366City: LAKEWOOD State: CO Zip: 80228**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**2 Number of Comments0 Number of Corrective Actions Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Chollett, Shannon		shannon.chollett@state.co.us	
Neidel, Kris		kris.neidel@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
291259	WELL	SI	01/01/2014	GW	081-07395	BM FEDERAL 13-12 (OWP)	EI

**General Comment:**

On November 14, 2023 ECMC OWP EPS Jim Hughes conducted a field inspection of the Entek BM Federal #13-12. For the most recent field inspection report of this facility, please refer to document #702502109.

**Inspected Facilities**Facility ID: 291259 Type: WELL API Number: 081-07395 Status: SI Insp. Status: EI**COGCC Comments**

Comment	User	Date
<p>On November 14, 2023 ECMC OWP EPS Jim Hughes conducted a field inspection of the Entek BM Federal #13-12. For the most recent field inspection report of this facility, please refer to Document #702502109.</p> <p>This field inspection resulted from Inspection Document #702502109. According to that document a cow knocked a valve open and the landowner closed it once the release was discovered. Spill report Document #403590563 was submitted by the ECMC OWP and Spill/Release Point ID #485479 was created.</p> <p>Soil samples were collected during this field inspection. One background sample was collected from undisturbed soil up-gradient of the well pad. A sample was collected from the damp area near the well head. Another sample was collected beyond any evidence of staining or flow to the northwest of the location. All samples were analyzed for Table 915-1 constituents. A soil sample location map and analytical results will be submitted with a Supplement Spill Report.</p>	hughesjo	11/29/2023

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
704900121	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6338257">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6338257</a>