

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/28/2023

Submitted Date:

11/29/2023

Document Number:

705000528

FIELD INSPECTION FORM

Loc ID 329141 Inspector Name: Maclaren, Joe On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

Findings:

- 3 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		ECMCInspections@Oxy.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
249124	WELL	SI	02/01/2021	OW	123-16926	HSR-VADMAN 3-34	PA
463372	Location	AC			-	HSR-VADNEY-63N66W-TANK 34NENW	EG

General Comment:

[ECMC Engineering Integrity Inspection; Flowline Inspection](#)
[Photos uploaded](#)

Inspected Facilities

Facility ID: 249124 Type: WELL API Number: 123-16926 Status: SI Insp. Status: PA

Flowline

#1	Type: Non-Well Site	of Lines
----	---------------------	----------

Flowline Description

Flowline Type: Non-Well Site Size: 2" Material: Carbon Steel
 Variance: Age: Contents:

Integrity Summary

Failures: Spills: Repairs Made:
 Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules(check all that apply)

1101. Installation and Reclamation 1102. Operations, Maintenance, and Repair 1103. Abandonment

Comment: Well is plugged and abandoned (HSR Vadman 3-34); ECMC form 42 notice of start of plugging operations doc #403529430 received on 09/14/2023. The facility/ tank battery has been decommissioned; tanks and equipment removed. On location flowlines have been removed; dump and process flowlines at facility/ battery are removed. No flowlines/ risers observed. Fenced excavations observed at PA well and facility/ battery areas. Excavation/ remediation work is in progress.

Corrective Action:

Date:

Facility ID: 463372 Type: Location API Number: - Status: AC Insp. Status: EG

COGCC Comments

Comment	User	Date
As outlined on COGCC form 19 spill report Doc #403604998 received on 11/22/2023: While conducting wellhead plugging and abandonment activities at the Vadman 3-34A wellhead, historically impacted soil was discovered at the wellhead. The volume of the release is unknown. Assessment activities are ongoing.	maclarej	11/29/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
705000532	Signage and fenced excavation at facility/ battery	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6338258
705000533	Fenced excavation at PA well	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6338260