

Inspection Photos
Location: Enterprise 16-1
Facility ID: 481042



Photo 1 –Well Site Placard at access road



Photo 2 – Well location looking south

Inspection Photos
Location: Enterprise 16-1
Facility ID: 481042



Photo 3 – Well location looking west



Photo 4 – Well location looking north/northwest

Inspection Photos
Location: Enterprise 16-1
Facility ID: 481042



Photo 5 – Well location looking east



Photo 6 – Access road leaving location

Inspection Photos
Location: Enterprise 16-1
Facility ID: 481042



Photo 7 – Access road



Photo 8 – Access road with riling and rutting