

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/29/2023

Submitted Date:

11/30/2023

Document Number:

713600430**FIELD INSPECTION FORM**Loc ID 324840 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 83130Name of Operator: STRACHAN EXPLORATION INCAddress: 383 INVERNESS PKWY, STE 360City: ENGLEWOOD State: CO Zip: 80112**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**6 Number of Comments5 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name   | Phone | Email                         | Comment |
|----------------|-------|-------------------------------|---------|
| Pesicka, Conor |       | conor.pesicka@state.co.us     |         |
| BEAR STACY     |       | stacy@strachanexploration.com |         |
| HARMS JASON    |       | jason@strachanexploration.com |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 213042      | WELL | PR     | 09/24/2007  | OW         | 061-06403 | WEINMAN 1-27  | RI          |

**General Comment:**

This is a follow up of the previous inspection #713600140.  
See attached photos and additional details within this report

**Location**Overall Good: ☐**Signs/Marker:**

|                    |   |       |            |
|--------------------|---|-------|------------|
| Type               | WELLHEAD  |       |            |
| Comment:           | The well sign is faded and does not meet the signage requirements. Previous corrective action is not completed.                       |       |            |
| Corrective Action: | Install sign to comply with Rule 605.d.   | Date: | 05/13/2023 |
| Type               | BATTERY   |       |            |
| Comment:           | The tank battery sign is faded and does not meet the signage requirements of Rule 605.e. Previous corrective action is not completed. |       |            |
| Corrective Action: | Install sign to comply with Rule 605.e.   | Date: | 08/24/2023 |

**Emergency Contact Number:**Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

|                    |  |        |  |                  |
|--------------------|--|--------|--|------------------|
| Type               | Area   | Volume |  |                  |
| Crude Oil          | Tank   |        |  |                  |
| Comment:           | There is oil stained soil behind (west side) the tank. |        |  |                  |
| Corrective Action: | Clean up per Rule 912.a.                               |        |  | Date: 11/29/2023 |

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

|                    |  |  |                  |
|--------------------|--|--|------------------|
| Type               | LOCATION   |  |                  |
| Comment:           | The fence around the tanks and production equipment is inadequate to prevent livestock entry and is not maintained. Previous corrective action is not completed. |  |                  |
| Corrective Action: | Comply with the fencing requirements per the 1002a rules.  |  | Date: 08/24/2023 |

**Tanks and Berms:**

|                    |   |          |           |         |        |  |
|--------------------|---|----------|-----------|---------|--------|--|
| Contents           | # | Capacity | Type      | Tank ID | SE GPS |  |
|                    | 3 |          | STEEL AST |         | ,      |  |
| Comment:           |   |          |           |         |        |  |
| Corrective Action: |   |          |           |         | Date:  |  |

**Paint**

|                  |                      |  |
|------------------|----------------------|--|
| Condition        | <input type="text"/> |  |
| Other (Content)  |                      |  |
| Other (Capacity) |                      |  |
| Other (Type)     |                      |  |

**Berms**

|       |            |                     |                     |             |
|-------|------------|---------------------|---------------------|-------------|
| Type  | Capacity   | Permeability (Wall) | Permeability (Base) | Maintenance |
| Earth | Inadequate | Walls Insufficient  | Base Insufficient   | Inadequate  |

Inspector Name: COSTA, RYAN

|                    |   |                  |
|--------------------|---|------------------|
| Comment:           | The berm around the tank battery is insufficient to contain a spill. Berms need to be compacted and built to be impermeable. Previous corrective action is not completed. |                  |
| Corrective Action: | Repair or install berms or other secondary containment devices per Rule 603.o.  | Date: 08/24/2023 |

**Venting:**

|                    |  |       |  |
|--------------------|--|-------|--|
| Yes/No             |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description       | URL   |
|--------------|-------------------|---|
| 713600431    | Inspection Photos | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6339879">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6339879</a> |