

# Interim Reclamation and Stormwater Inspection

Date: 11/09/2023

Operator: Bonanza Creek ENergy Operating  
Company LLC. - 8960

Location ID: 466974

Inspection Document #: 713900099

Weld County, CO

Logan Hansen  
Reclamation Specialist, ECMC



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Photos  
Location Name: Antelope C-33  
Location ID: 466974



**Photo 1.** The photo was taken at the entrance to the location of the location sign facing Southeast.



**Photo 2.** The photo was taken at the well location facing West. The photo illustrates the interim areas have been mowed and there are evidence of perennials as well undesirable weeds.

Inspection Photos  
Location Name: Antelope C-33  
Location ID: 466974



**Photo 3.** The photo was taken at the well location facing Southwest. The photo illustrates debris including straw wattle, concrete blocks and stakes as well as some accumulation of undesirable vegetation.

**Photo 4.** The photo was taken at the well location facing North. Refer to the comment for photo 3.

Inspection Photos  
Location Name: Antelope C-33  
Location ID: 466974



**Photo 5.** The photo was taken at the well location facing South. The photo illustrates areas of bare soil being torn up by wheel tracking in the interim areas.

**Photo 6.** The photo was taken at the well location facing South. The photo illustrates the slope off the active pad is unprotected from erosion by vegetation or BMP's.

Inspection Photos  
Location Name: Antelope C-33  
Location ID: 466974



**Photo 7.** The photo was taken at the entrance to the well location facing Northwest of the access road.