

Final Reclamation Inspection

November 16th, 2023

Operator: Hilcorp Energy Company- 10133

Location ID: 333494

Inspection Document #: 714000138

La Plata County, CO

Township: NWSE 32 34N 10W M

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Argenta 34-10 32-2, 32-2A
Location ID: 333494



Photo 1. View of the project area taken from the entrance facing center.



API #: 067-08246, 09383

Inspection Photos
Location Name :Argenta 34-10 32-2, 32-2A
Location ID: 333494



Photo 2. View of failing stormwater BMPs and forming gully erosion observed on the western fill slope/interim area of the disturbance.



Inspection Photos
Location Name: Argenta 34-10 32-2, 32-2A
Location ID: 333494



Photo 3. View of additional rill erosion forming on the western fill slope of the disturbance.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #:067-05515

Inspection Photos
Location Name : Argenta 34-10 32-2, 32-2A
Location ID: 333494



Photo 4. View of rill erosion and failing stormwater BMPs observed in the southern interim area of the disturbance.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #:067-05515

Inspection Photos
Location Name : Argenta 34-10 32-2, 32-2A
Location ID: 333494



Photo 5. Additional rill erosion forming downslope of failing stormwater BMPs in the southern interim reclamation area.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #:067-05515