

Final Reclamation Inspection

November 20th, 2023

Operator: Hilcorp Energy Company- 10133

Location ID: 325510

Inspection Document #: 714000145

La Plata County, CO

Township: NENW 4 33N 10W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Davis Gas Unit 1
Location ID: 325510



Photo 1. View of the project area taken from the entrance facing center.

Inspection Photos
Location Name : Davis Gas Unit 1
Location ID: 325510



Photo 2. View of stormwater BMPs installed in the western interim reclamation area by the access road.

Inspection Photos
Location Name : Davis Gas Unit 1
Location ID: 325510




Photo 3. View of stormwater BMPs installed in the eastern interim reclamation area.

Inspection Photos
Location Name : Davis Gas Unit 1
Location ID: 325510



Photo 4. Installed BMPs observed around the location are not per good engineering practice, operator has used round river stone rather than large angular rock. Round rock may increase erosion and scouring in these areas.