

Inspection Photos

API: 061-06296

Operator: STRACHAN EXPLORATION INC

Inspection Date: 11/29/2023



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing toward the wellsite.



Inspection Photos



Photo 2. Facing northeast toward the tank battery.



Inspection Photos



Photo 3. The fence around the tank battery is inadequate to prevent livestock entry and is not maintained. Previous corrective action was not completed.



Inspection Photos



Photo 4. The berm is inadequate to contain a spill as it is piled up against the tank and would spill over the berm along this side. Previous corrective action was not completed.

