

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/29/2023

Submitted Date:

12/01/2023

Document Number:

713600438**FIELD INSPECTION FORM**Loc ID 324832 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 83130Name of Operator: STRACHAN EXPLORATION INCAddress: 383 INVERNESS PKWY, STE 360City: ENGLEWOOD State: CO Zip: 80112**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
HARMS, JASON		jharms@strachanexploration.com	
BEAR STACY		stacy@strachanexploration.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
213007	WELL	PR	08/14/1987	GW	061-06368	LAS ANIMAS 1-1	RI

General Comment:

This is a follow up of the previous inspections; #690204387, #713600142.
See attached photos and additional details within this report.

LocationOverall Good: ☐**Signs/Marker:**

Type			
Comment:	Labeling on tanks has been updated.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	TANK BATTERY				
Comment:	The fence around the tanks is missing or inadequate to prevent livestock entry. Corrective action will remain out of compliance until completed.				
Corrective Action:	Comply with the fencing requirements per the 1002a rules			Date:	06/29/2023

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
	2		Open Top		
Comment:	Netting has been installed on both open top tanks.				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth		Walls Insufficient		
Comment:	The berm around the tank has been built up however soils were not compacted to be impermeable. There are already animal burroughs and erosion of the berms.			
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 603.o.			Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713600439	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6340844