

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/29/2023

Submitted Date:

12/01/2023

Document Number:

707602120

FIELD INSPECTION FORM

Loc ID 326889 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 2001 16TH STREET SUITE 900
City: DENVER State: CO Zip: 80202

Findings:

- 11 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		rbucogccinspectionreports@chevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
246021	WELL	TA	11/19/2021	GW	123-13817	TREBOR B11-6	TA

General Comment:

This is a WELL inspection.
Well(s): 1: Temporarily Abandoned | TA.
Battery: Inactive | Shut-down.

Centralized Battery serves 5 Location IDs (326889, 326886, 414330, 414332, 414334).
(Well(s): 5: Temporarily Abandoned | TA).

Centralized Battery Formerly served 2 Location IDs (310601, 323768).
(Well(s): 2: Plugged & Abandoned | PA).

Centralized Battery serves 1 Tank Battery Facility ID (Pending).

Reference:
A.) Field Inspection Report doc. #707602120 and/or Location ID #326889 for TA Well(s) info.
B.) Field Inspection Report doc. #707602122 and/or Location ID #326886 for TA Well(s) info.
C.) Field Inspection Report doc. #707602124 and/or Location ID #414330 for TA Well(s) info.
D.) Field Inspection Report doc. #707602126 and/or Location ID #414332 for TA Well(s) info.
E.) Field Inspection Report doc. #707602129 and/or Location ID #414334 for TA Well(s) info.
F.) Field Inspection Report doc. #707602131 and/or Location ID #310601 for PA Well(s) info.
G.) Field Inspection Report doc. #707602133 and/or Location ID #326889 for Battery / Facility, Equipment info.

Location			
Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action:		Date:	
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
Good Housekeeping:			
Type	WEEDS		
Comment:	Overgrown vegetation at wellsite. Refer to Rule 606.c for guidance.		
Corrective Action:	*Remove, manage, & control overgrown vegetation around wellsite. Comply with Rule 606.c. Corrective Action date: 01/02/2024. (30-days). See photo #1. *Please attach photo(s) to FIRR to verify Corrective Action(s) have been resolved.		Date: <u>01/02/2024</u>
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	Iron panel.		
Corrective Action:		Date:	
Equipment:			
Type: Other	# 1		corrective date
Comment:	Wellhead: w/ Master, casing valves.		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Appears plumbed to surface.		
Corrective Action:		Date:	
Type: Plunger Lift	# 0		
Comment:	Temporarily Abandoned TA, Equipment removed.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.416741,-104.523329
Comment:	Centralized Battery serves 5 Location IDs (326889, 326886, 414330, 414332, 414334). (Well(s): 5: Temporarily Abandoned TA). Centralized Battery serves 1 Tank Battery Facility ID (Pending).				
Corrective Action:					Date:

Paint

Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				
				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			
			Date:

Flaring:

Type			
Comment:			
Corrective Action:			
			Date:

Inspected Facilities

Facility ID: 246021 Type: WELL API Number: 123-13817 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Temporarily Abandoned | TA.
Disconnected from flowline.
Battery: Inactive | Shut-down.
Locked-Out, Tagged-Out | LOTO.
Blue TA tag posted.
CECMC records last production: 04/2020.

Form 4 on file. TA date: 11/03/2021. Approved.
DH-CIBP set.
Form 21 MIT on file. MIT date: 11/4/2021. Approved.
Form 6A on file. Out-of-Svc Designation.
Date: 04/01/2020. Approved.

Corrective Action:

Date: _____

BradenHead

Date of Last Brhd Test: 04/10/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____
End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>CECMC Inspection Report Summary:</p> <p>On WED 11/29/2023 at approximately 14:22 hrs. I, Bret Evins, conducted an onsite inspection at: Operator Name: NOBLE ENERGY INC Location Name: TREBOR-65N64W/11SEW Location ID: 326889 Well Name(s): Trebor B11-6 API: 123-13817. Location County: Weld County, Colorado Weather: Mostly Sunny, damp w/ some snow from prior storm.</p> <p>While there, I observed: Well(s): 1: Temporarily Abandoned TA. Battery: Inactive Shut-down.</p> <p>Centralized Battery serves 5 Location IDs (326889, 326886, 414330, 414332, 414334). (Well(s): 5: Temporarily Abandoned TA).</p> <p>Centralized Battery Formerly served 2 Location IDs (310601, 323768). (Well(s): 2: Plugged & Abandoned PA).</p> <p>Centralized Battery serves 1 Tank Battery Facility ID (Pending).</p> <p>Reference: A.) Field Inspection Report doc. #707602120 and/or Location ID #326889 for TA Well(s) info. B.) Field Inspection Report doc. #707602122 and/or Location ID #326886 for TA Well(s) info. C.) Field Inspection Report doc. #707602124 and/or Location ID #414330 for TA Well(s) info. D.) Field Inspection Report doc. #707602126 and/or Location ID #414332 for TA Well(s) info. E.) Field Inspection Report doc. #707602129 and/or Location ID #414334 for TA Well(s) info. F.) Field Inspection Report doc. #707602131 and/or Location ID #310601 for PA Well(s) info. G.) Field Inspection Report doc. #707602133 and/or Location ID #326889 for Battery / Facility, Equipment info.</p> <p>During this inspection the following possible compliance issue(s) were observed: 1.) Overgrown vegetation at wellsite. Refer to Rule 606.c for guidance. *Remove, manage, & control overgrown vegetation around wellsite. Comply with Rule 606.c. Corrective Action date: 01/02/2024. (30-days). See photo #1.</p> <p>*Please attach photo(s) to FIRR to verify Corrective Action(s) have been resolved.</p> <p>*A follow up on this site inspection will be conducted to ensure that compliance issues have been corrected to comply with CECMC rules.</p> <p>This is a summary of the inspection report.</p>	<p>evinsb</p>	<p>12/01/2023</p>

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707602121	Site photo(s)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6341042