

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/30/2023

Submitted Date:

12/01/2023

Document Number:

707602117

**FIELD INSPECTION FORM**

Loc ID 306348 Inspector Name: Evins, Bret On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 100322  
Name of Operator: NOBLE ENERGY INC  
Address: 2001 16TH STREET SUITE 900  
City: DENVER State: CO Zip: 80202

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

7 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@chevron.onmicrosoft.com	<a href="#">All Inspections</a>
,		dnr_cogccengineering@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
288025	WELL	SI	09/01/2017	OW	123-24494	HOWARD USX A 9-13	PA

**General Comment:**

This is a **PLUGGED & ABANDONED WELL** inspection.  
Well(s): 1: Plugged & Abandoned | PA.  
Plugging Operations: Cementing; Initial plug(s).  
Battery: Inactive. Shut-down.  
Inactive Battery SE corner GPS coordinates: 40.496131 / -104.564086  
Well GPS coordinates: 40.495090 / -104.562070

Location			
<b>Lease Road:</b>			
	Type Access		
comment:	Adequate		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
	Type OTHER		
Comment:	Jobsite entrance & safety signage posted.		
Corrective Action:			Date:
	Type BATTERY		
Comment:			
Corrective Action:			Date:
	Type WELLHEAD		
Comment:			
Corrective Action:			Date:
<b>Emergency Contact Number:</b>			
Comment:			
Corrective Action:			Date: _____
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Equipment:</b>			
Type: Plunger Lift	# 0		corrective date
Comment:	Plugged & Abandoned   PA. Equipment removed.		
Corrective Action:			Date:
<b>Venting:</b>			
Yes/No			
Comment:			
Corrective Action:			Date:
<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:			Date:

**Inspected Facilities**

Facility ID: 288025 Type: WELL API Number: 123-24494 Status: SI Insp. Status: PA

**Cement**

Cement Contractor

Contractor Name: A-Plus Well

Contractor Phone: \_\_\_\_\_

Surface Casing

Cement Volume (sx): \_\_\_\_\_

Circulate to Surface: \_\_\_\_\_

Cement Fall Back: \_\_\_\_\_

Top Job, 1" Volume: \_\_\_\_\_

Intermediate Casing

Cement Volume (sxs): \_\_\_\_\_

Good Return During Job: \_\_\_\_\_

Production Casing

Cement Volume (sx): \_\_\_\_\_

Good Return During Job: \_\_\_\_\_

Plugging Operations

Depth Plugs(feet range): 6,683'-2,522'

Cement Volume (sx): 12 sxs

Good Return During Job: \_\_\_\_\_

Cement Type: Class "G" Neat 15.8#

Comment:

Workover Contractor: A-Plus Well Services, Rig #12.  
 Cement Contractor: A-Plus Well Services.

Reference:  
 Form 6N on file. Notice of Intent to Abandon date: 10/04/2023. Approved.  
 Form 42 on file. Notice of MIRU. Start Date: 11/30/2023. Approved.  
 Form 42 on file. Notice of Plugging Operations. Start Date: 12/01/2023. Approved.

2023/11/30:  
 Plugging Operations: Cementing; Initial plug(s).  
 2023/11/30: JSA attached as photo to this report.

SAFETY/JSA MEETING. SWC/SYLA, LOCK/OUT TAG OUT. START EQUIPMENT.  
 CHECK GROUNDING (WSEA 2-A)  
 CHECK PSI. CSG O PSI. TBG O PSI. SURFACE O PSI  
 OPEN WELL TO TANK. FLOW CHECK 15 MIN. WELL STATIC (WSEA10-A)  
 TOO H W/2 3/8 4. 7# J-55 EUE TBG, LD 133 JTS  
 RUI/VL, PU 4.511.6# 10K CIBP, VERIFY DEPTH >JV/CCL. SET CIBP@6683  
 SPOT 2 S"-CS G-NEAT CMT @1.15 YIELD ON CIBP  
 LOAD HOLEW/38 BBLs 8.3# FRESH WATER, TEST TO 1500 PSI. HELD FOR 15 MIN.  
 STARTING'  
 PSI 1500. ENDING PSI 1500. 0% DROP IN PSI. GOOD TEST (WSE:A 10-Bi  
 PU 4.511.6# 10K CIBP. VERIFY DEPTH W/CCL. SET CIBP@2522. RDWL  
 TIH W/80 JTS OF 2 3/8 4. 7# J-55 EUE TBG TO 2522  
 TEST PUMP LINES. PUMP BALANCE PLUG AS FOLLOWS. PUMP 10 BBLs  
 CHEI-IWASH. 10  
 SACS OR 2 BBLs OF 15.8# G-NEAT CMT @1.15 YIELD, DISPLACE 9.2 BBLs FRESH  
 WATER,  
 EST CMT 2522-2390  
 TOO H LD 19JTS OF 2 3/8 4.7#J-55 EUE TBG. REVERSE OUT @1912 W/20 BBLs  
 FRESH  
 WATER, NO CMT IN RETURNS. TOO H LD60 JTS  
 SWL DRAIN PUMP & LINES, HELD DEBRIEF W/CREW.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass			Material Handling And Spill Prevention	Pass	

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<p><b>CECMC Inspection Report Summary:</b></p> <p>On THU 11/30/2023 at approximately 12:06 hrs. I, Bret Evins, conducted an on-site inspection at:                      Operator Name: NOBLE ENERGY INC                      Location Name: HOWARD USX A-66N64W/9SWSW                      Location ID: 306348                      Well Name(s):                      Howard USX A 9-13.                      API:                      123-24494.                      Location County: Weld County, Colorado                      Weather: Partly Sunny, damp w/ some snow cover from prior storm.</p> <p>While there, I observed:                      Well(s): 1: Plugged &amp; Abandoned   PA.                      Plugging Operations: Cementing; Initial plug(s).                      Battery: Inactive. Shut-down.                      Inactive Battery SE corner GPS coordinates: 40.496131 / -104.564086                      Well GPS coordinates: 40.495090 / -104.562070</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	12/01/2023

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707602119	Site photo(s)	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6341041">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6341041</a>