

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/29/2023

Submitted Date:

12/01/2023

Document Number:

707602122

**FIELD INSPECTION FORM**

Loc ID 326886	Inspector Name: Evins, Bret	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED  <b>Findings:</b> 10 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested
<b>Operator Information:</b> OGCC Operator Number: 100322 Name of Operator: NOBLE ENERGY INC Address: 2001 16TH STREET SUITE 900 City: DENVER State: CO Zip: 80202				
<b>ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE</b>				

<b>Contact Information:</b>			
Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Inspections

<b>Inspected Facilities:</b>							
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
246018	WELL	TA	01/01/2022	OW	123-13814	TREBOR B11-3	TA

<b>General Comment:</b> <p>This is a WELL inspection.          Well(s): 1: Temporarily Abandoned   TA.          Battery: Inactive   Shut-down.</p> <p>Centralized Battery serves 5 Location IDs          (326889, 326886, 414330, 414332, 414334).          (Well(s): 5: Temporarily Abandoned   TA).</p> <p>Centralized Battery Formerly served 2 Location IDs          (310601, 323768).          (Well(s): 2: Plugged &amp; Abandoned   PA).</p> <p>Centralized Battery serves 1 Tank Battery Facility ID          (Pending).</p> <p>Reference:          A.) Field Inspection Report doc. #707602120 and/or Location ID #326889 for TA Well(s) info.          B.) Field Inspection Report doc. #707602122 and/or Location ID #326886 for TA Well(s) info.          C.) Field Inspection Report doc. #707602124 and/or Location ID #414330 for TA Well(s) info.          D.) Field Inspection Report doc. #707602126 and/or Location ID #414332 for TA Well(s) info.          E.) Field Inspection Report doc. #707602129 and/or Location ID #414334 for TA Well(s) info.          F.) Field Inspection Report doc. #707602131 and/or Location ID #310601 for PA Well(s) info.          G.) Field Inspection Report doc. #707602133 and/or Location ID #326889 for Battery / Facility, Equipment info.</p>
---

**Location****Lease Road:**

Type	Access		
comment:	Adequate		
Corrective Action	L	Date:	

Overall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:		
Corrective Action:		Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Iron panel.		
Corrective Action:		Date:	

**Equipment:**

Type: Bradenhead	# 1		corrective date
Comment:	Appears plumbed to surface.		
Corrective Action:		Date:	
Type: Plunger Lift	# 0		
Comment:	Temporarily Abandoned   TA. Equipment removed.		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Wellhead: w/ Master, casing valves.		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.416741,-104.523329

Comment:	Centralized Battery serves 5 Location IDs (326889, 326886, 414330, 414332, 414334). (Well(s): 5: Temporarily Abandoned   TA).  Centralized Battery serves 1 Tank Battery Facility ID (Pending).	
Corrective Action:		Date:

**Paint**

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 246018 Type: WELL API Number: 123-13814 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily AbandonedReminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Temporarily Abandoned | TA.  
Disconnected from flowline.  
Battery: Inactive | Shut-down.  
Locked-Out, Tagged-Out | LOTO.  
Blue TA tag posted.  
CECMC records last production: 04/2020.

Form 4 on file. TA date: 11/01/2021. Approved.  
DH-CIBP set.  
Form 21 MIT on file. MIT date: 11/03/2021. Approved.  
Form 6A on file. Out-of-Svc Designation.  
Date: 04/01/2020. Approved.

Corrective Action: Date: **BradenHead**Date of Last Brhd Test: 04/09/2023Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0Fluid Type: End Surf Csg Pressure: 0Comment: Corrective Action: Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment:

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>CECMC Inspection Report Summary:</p> <p>On WED 11/29/2023 at approximately 14:32 hrs. I, Bret Evins, conducted an onsite inspection at:  Operator Name: NOBLE ENERGY INC  Location Name: TREBOR-65N64W/11NENW  Location ID: 326886  Well Name(s):  Trebor B11-3  API:  123-13814.  Location County: Weld County, Colorado  Weather: Mostly Sunny, damp w/ some snow from prior storm.</p> <p>While there, I observed:  Well(s): 1: Temporarily Abandoned   TA.  Battery: Inactive   Shut-down.</p> <p>Centralized Battery serves 5 Location IDs  (326889, 326886, 414330, 414332, 414334).  (Well(s): 5: Temporarily Abandoned   TA).</p> <p>Centralized Battery Formerly served 2 Location IDs  (310601, 323768).  (Well(s): 2: Plugged &amp; Abandoned   PA).</p> <p>Centralized Battery serves 1 Tank Battery Facility ID  (Pending).</p> <p>Reference:  A.) Field Inspection Report doc. #707602120 and/or Location ID #326889 for TA Well(s) info.  B.) Field Inspection Report doc. #707602122 and/or Location ID #326886 for TA Well(s) info.  C.) Field Inspection Report doc. #707602124 and/or Location ID #414330 for TA Well(s) info.  D.) Field Inspection Report doc. #707602126 and/or Location ID #414332 for TA Well(s) info.  E.) Field Inspection Report doc. #707602129 and/or Location ID #414334 for TA Well(s) info.  F.) Field Inspection Report doc. #707602131 and/or Location ID #310601 for PA Well(s) info.  G.) Field Inspection Report doc. #707602133 and/or Location ID #326889 for Battery / Facility, Equipment info.</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	12/01/2023

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707602123	Site photo(s)	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6341043">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6341043</a>