

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/29/2023

Submitted Date:

12/01/2023

Document Number:

707602133

**FIELD INSPECTION FORM**

Loc ID: 326889 Inspector Name: Evins, Bret On-Site Inspection:  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 100322  
Name of Operator: NOBLE ENERGY INC  
Address: 2001 16TH STREET SUITE 900  
City: DENVER State: CO Zip: 80202

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

13 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
		rbucogccinspectionreports@chevron.onmicrosoft.com	All Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
326889	LOCATION	AC			-	TREBOR-65N64W 11SENW	IO

**General Comment:**

This is a BATTERY inspection.  
Well(s): 5: Temporarily Abandoned | TA.  
Battery: Inactive | Shut-down.

Centralized Battery serves 5 Location IDs (326889, 326886, 414330, 414332, 414334).  
(Well(s): 5: Temporarily Abandoned | TA).

Centralized Battery Formerly served 2 Location IDs (310601, 323768).  
(Well(s): 2: Plugged & Abandoned | PA).

Centralized Battery serves 1 Tank Battery Facility ID (Pending).

Reference:  
A.) Field Inspection Report doc. #707602120 and/or Location ID #326889 for TA Well(s) info.  
B.) Field Inspection Report doc. #707602122 and/or Location ID #326886 for TA Well(s) info.  
C.) Field Inspection Report doc. #707602124 and/or Location ID #414330 for TA Well(s) info.  
D.) Field Inspection Report doc. #707602126 and/or Location ID #414332 for TA Well(s) info.  
E.) Field Inspection Report doc. #707602129 and/or Location ID #414334 for TA Well(s) info.  
F.) Field Inspection Report doc. #707602131 and/or Location ID #310601 for PA Well(s) info.  
G.) Field Inspection Report doc. #707602133 and/or Location ID #326889 for Battery / Facility, Equipment info.

Location			
<b>Lease Road:</b>			
Type	Access		
comment:	Adequate		
Corrective Action:		Date:	
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	Middle crude oil tank Contents / Capacity labels & NFPA placard needs replaced.		
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	TANK BATTERY		
Comment:	Braided wire.		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Surrounded by earth berms.		
Corrective Action:		Date:	
<b>Equipment:</b>			
Type: Ancillary equipment	# 2		corrective date
Comment:	Battery site: 2: ECD scrubber(s).		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Gas Sales: Calibration card(s) indicates calibration <= 1 year. Last calibration: 09/07/2023. Inactive, NO production.		
Corrective Action:		Date:	
Type: Emission Control Device	# 3		

Comment: 2: Crude storage vapor line combustor(s). Controls crude oil tank(s) vapors. Pilots: OFF   Shut-down. 1: Separator vapor line combustor(s). Controls separator(s) vapors. Pilots: OFF   Shut-down.			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:		Date:	
Type: Pig Station	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		,
Comment: Centralized Battery serves 5 Location IDs (326889, 326886, 414330, 414332, 414334). (Well(s): 5: Temporarily Abandoned   TA).  Centralized Battery serves 1 Tank Battery Facility ID (Pending).					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLs	CONCRETE SUMP/VAULT		,
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	53 Bbls.
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment: Berms shared w/ crude oil tank(s), produced H2O vault(s).					
Corrective Action:				Date:	

**Contents**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	5	300 BBLs	STEEL AST		40.416741,-104.523329

Comment:					
Corrective Action:				Date:	

**Paint**

Condition	Adequate	
-----------	----------	--

Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment: Berms shared w/ crude oil tank(s), produced H2O vault(s).					
Corrective Action:				Date:	

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 326889 Type: LOCATION API Number: - Status: AC Insp. Status: IO

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<p><b>CECMC Inspection Report Summary:</b></p> <p>On WED 11/29/2023 at approximately 15:23 hrs. I, Bret Evins, conducted an onsite inspection at:                      Operator Name: NOBLE ENERGY INC                      Location Name: TREBOR-65N64W/11SEW                      Location ID: 326889                      Well Name(s):                      Trebor B11-6, Trebor B11-3, Trebor B 11-21, Trebor B 11-18, Trebor B 11-20.                      API:                      123-13817, 123-13814, 123-30729, 123-30730, 123-30731.                      Location County: Weld County, Colorado                      Weather: Mostly Sunny, damp w/ some snow from prior storm.</p> <p>While there, I observed:                      Well(s): 5: Temporarily Abandoned   TA.                      Battery: Inactive   Shut-down.</p> <p>Centralized Battery serves 5 Location IDs (326889, 326886, 414330, 414332, 414334).                      (Well(s): 5: Temporarily Abandoned   TA).</p> <p>Centralized Battery Formerly served 2 Location IDs (310601, 323768).                      (Well(s): 2: Plugged &amp; Abandoned   PA).</p> <p>Centralized Battery serves 1 Tank Battery Facility ID (Pending).</p> <p>Reference:                      A.) Field Inspection Report doc. #707602120 and/or Location ID #326889 for TA Well(s) info.                      B.) Field Inspection Report doc. #707602122 and/or Location ID #326886 for TA Well(s) info.                      C.) Field Inspection Report doc. #707602124 and/or Location ID #414330 for TA Well(s) info.                      D.) Field Inspection Report doc. #707602126 and/or Location ID #414332 for TA Well(s) info.                      E.) Field Inspection Report doc. #707602129 and/or Location ID #414334 for TA Well(s) info.                      F.) Field Inspection Report doc. #707602131 and/or Location ID #310601 for PA Well(s) info.                      G.) Field Inspection Report doc. #707602133 and/or Location ID #326889 for Battery / Facility, Equipment info.</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	<p>evinsb</p>	<p>12/01/2023</p>

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707602134	Site photo(s)	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6341048">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6341048</a>