

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/30/2023

Submitted Date:

12/02/2023

Document Number:

707602155**FIELD INSPECTION FORM**Loc ID 326701 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: **Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 2001 16TH STREET SUITE 900City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:13 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
432615	WELL	TA	03/01/2022	OW	123-37192	LEEROY B11-79HNM	TA
432616	WELL	PR	04/01/2023	OW	123-37193	TREBOR B11-65-1HN	PR
432617	WELL	PR	03/16/2022	OW	123-37194	JENKINS B11-79-1HCM	PR

General Comment:

This is a WELL inspection.
Well(s): 2: Producing | PR ; 1: Temporarily Abandoned | TA.
Battery: Active.

Centralized Battery serves 1 Location ID
(326701).
(Well(s): 2: Producing | PR ; 1: Temporarily Abandoned | TA).

Centralized Battery Formerly served 1 Location ID
(326701).
(Well(s): 1: Plugged & Abandoned | PA).

Centralized Battery serves 1 Tank Battery Facility ID
(Pending).

Reference:
A.) Field Inspection Report doc. #707602155 and/or Location ID #326701
for PR, TA Well(s) info.
B.) Field Inspection Report doc. #707602157 and/or Location ID #326701
for PA Well(s) info.
C.) Field Inspection Report doc. #707602159 and/or Location ID #326701
for Battery / Facility, Equipment info.

Location

Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action:		Date:	

Overall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:	3: Wellsites.		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			
	Date:		

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	3: Wellsites. Iron panel.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bradenhead	# 3		
Comment:	3: Wellsites. Appears plumbed to surface.		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Leeroy B11-79HNM: Wellhead: w/ Master & casing valves.		
Corrective Action:		Date:	
Type: Plunger Lift	# 2		
Comment:	2: Wellsites.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.411570,-104.526790

Comment:	Centralized Battery serves 1 Location ID (326701). (Well(s): 2: Producing PR ; 1: Temporarily Abandoned TA.). Centralized Battery serves 1 Tank Battery Facility ID (Pending).		
Corrective Action:		Date:	

Paint

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 432615 Type: WELL API Number: 123-37192 Status: TA Insp. Status: TA

Idle Well

Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Temporarily Abandoned | TA.
Disconnected from flowline.
Locked-Out, Tagged-Out | LOTO.
Blue TA tag posted.
CECMC records last production: 12/2017.

Form 4 on file. TA date: 12/01/2020. Approved.
DH-CIBP set.
Form 21 MIT on file. MIT date: 12/17/2020. Approved.
Form 6A on file. Out-of-Svc Designation.
Date: 03/14/2020. Approved.

Corrective Action: Date:

BradenHead

Date of Last Brhd Test: 07/21/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE
End Surf Csg Pressure: 0

Comment:

Corrective Action: Date:

Facility ID: 432616 Type: WELL API Number: 123-37193 Status: PR Insp. Status: PR

Producing Well

Comment: Producing | PR.

Corrective Action: Date:

BradenHead

Date of Last Brhd Test: 04/20/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:
End Surf Csg Pressure: 0

Comment:

Corrective Action: Date:

Facility ID: 432617 Type: WELL API Number: 123-37194 Status: PR Insp. Status: PR

Producing Well

Comment: Producing | PR.

Corrective Action: Date:

BradenHead			
Date of Last Brhd Test: 07/21/2023		Annual Brhd Completed? Yes	
Last Brhd Test Results		Initial Surf Csg Pressure: 0	Fluid Type: NONE
		End Surf Csg Pressure: 0	
Comment:			
Corrective Action:			Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>CECMC Inspection Report Summary:</p> <p>On THU 11/30/2023 at approximately 14:54 hrs. I, Bret Evins, conducted an onsite inspection at: Operator Name: NOBLE ENERGY INC Location Name: TREBOR/B11-65-1HN Location ID: 326701 Well Name(s): Leeroy B11-79HNM, Trebor B11-65-1HN, Jenkins B11-79-1HCM. API: 123-37192, 123-37193, 123-37194. Location County: Weld County, Colorado Weather: Partly Sunny, damp w/ some snow from prior storm.</p> <p>While there, I observed: Well(s): 2: Producing PR ; 1: Temporarily Abandoned TA. Battery: Active.</p> <p>Centralized Battery serves 1 Location ID (326701). (Well(s): 2: Producing PR ; 1: Temporarily Abandoned TA).</p> <p>Centralized Battery Formerly served 1 Location ID (326701). (Well(s): 1: Plugged & Abandoned PA).</p> <p>Centralized Battery serves 1 Tank Battery Facility ID (Pending).</p> <p>Reference: A.) Field Inspection Report doc. #707602155 and/or Location ID #326701 for PR, TA Well(s) info. B.) Field Inspection Report doc. #707602157 and/or Location ID #326701 for PA Well(s) info. C.) Field Inspection Report doc. #707602159 and/or Location ID #326701 for Battery / Facility, Equipment info.</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	12/02/2023

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707602156	Site photo(s)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6341423

