

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/30/2023

Submitted Date:

12/02/2023

Document Number:

707602159

FIELD INSPECTION FORM

Loc ID 326701 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 2001 16TH STREET SUITE 900
City: DENVER State: CO Zip: 80202

Findings:

18 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
326701	LOCATION	AC			-	TREBOR B11-65-1HN	AO

General Comment:

This is a BATTERY inspection.
Well(s): 2: Producing | PR ; 1: Temporarily Abandoned | TA.
Battery: Active.

Centralized Battery serves 1 Location ID (326701).
(Well(s): 2: Producing | PR ; 1: Temporarily Abandoned | TA).

Centralized Battery Formerly served 1 Location ID (326701).
(Well(s): 1: Plugged & Abandoned | PA).

Centralized Battery serves 1 Tank Battery Facility ID (Pending).

Reference:
A.) Field Inspection Report doc. #707602155 and/or Location ID #326701 for PR, TA Well(s) info.
B.) Field Inspection Report doc. #707602157 and/or Location ID #326701 for PA Well(s) info.
C.) Field Inspection Report doc. #707602159 and/or Location ID #326701 for Battery / Facility, Equipment info.

Location			
Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	CONTAINERS		
Comment:	Battery site: Methanol (2). Placards.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	IGNITOR/COMBUSTOR		
Comment:	Partial iron pipe.		
Corrective Action:			Date:
Type	SEPARATOR		
Comment:	Surrounded by metal berms.		
Corrective Action:			Date:
Equipment:			
Type: VRU	# 1		corrective date
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 5		
Comment:	attery site: 2: Methanol pump(s), tank(s) w/ drip containment. Placards. 1: Solar power bank. 2: ECD scrubber(s).		

Corrective Action:		Date:	
Type: Gas Meter Run	# 6		
Comment:	<p>2: Gas Sales Master. Calibration card(s) indicates calibration <= 1 year. Last calibration: 09/19/2023. Active, w/ production.</p> <p>3: Gas Sales Allocation. Calibration card(s) indicates calibration <= 1 year. Last calibration: 05/17/2023. Active.</p> <p>1: Gas Buyback, VRU. Calibration card(s) indicates calibration <= 1 year. Last calibration: 05/17/2023. Active.</p>		
Corrective Action:		Date:	
Type: VRT	# 1		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 3		
Comment:	<p>Crude, produced H2O storage, Facility vapor line combustor(s). Controls crude oil, produced H2O tank(s), Facility vapors. Pilots: ON.</p>		
Corrective Action:		Date:	
Type: Other	# 3		
Comment:	<p>Battery site: Sand traps.</p>		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 6		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 9		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		
Comment:	<p>Centralized Battery serves 1 Location ID (326701). (Well(s): 2: Producing PR ; 1: Temporarily Abandoned TA.).</p> <p>Centralized Battery serves 1 Tank Battery Facility ID (Pending).</p>				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:				Date:	
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		40.411957,-104.526808
Comment: Labeled: Maintenance tank.				Date:	
Corrective Action:				Date:	
<u>Paint</u>					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
<u>Berms</u>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:				Date:	
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	3	300 BBLS	FIBERGLASS AST		
Comment: Partial insulated.				Date:	
Corrective Action:				Date:	
<u>Paint</u>					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
<u>Berms</u>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment: Berms shared w/ crude oil tank(s), produced H2O tank(s), vault(s).				Date:	
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	4	<100 BBLS	CONCRETE SUMP/VAULT		
Comment:				Date:	
Corrective Action:				Date:	
<u>Paint</u>					
Condition					
Other (Content)					
Other (Capacity)					

Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate		
Comment: Berms shared w/ crude oil tank(s), produced H2O tank(s), vault(s).						
Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	10	300 BBLs	STEEL AST		40.411570,-104.526790	
Comment: East Bank: 7 Equalizer line(s) connect 6 of 7 crude oil tank(s). West Bank: 3 Equalizer line(s) connect crude oil tank(s).						
Corrective Action:					Date:	
Paint						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate		
Comment: Berms shared w/ crude oil tank(s), produced H2O tank(s), vault(s).						
Corrective Action:					Date:	
Venting:						
Yes/No	NO					
Comment:						
Corrective Action:					Date:	
Flaring:						
Type						
Comment:						
Corrective Action:					Date:	

Inspected Facilities

Facility ID: 326701 Type: LOCATION API Number: - Status: AC Insp. Status: AO

Reclamation - Storm Water - Pit						
Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	
Comment: <input style="width: 90%;" type="text"/>						
Corrective Action: <input style="width: 95%;" type="text"/>					Date: _____	
Pits: <input type="checkbox"/> NO SURFACE INDICATION OF PIT						

COGCC Comments		
Comment	User	Date
<p>CECMC Inspection Report Summary:</p> <p>On THU 11/30/2023 at approximately 15:38 hrs. I, Bret Evins, conducted an onsite inspection at: Operator Name: NOBLE ENERGY INC Facility Name: Pending Facility ID: Pending Location Name: TREBOR/B11-65-1HN Location ID: 326701 Well Name(s): Leeroy B11-79HNM, Trebor B11-65-1HN, Jenkins B11-79-1HCM. API: 123-37192, 123-37193, 123-37194. Location County: Weld County, Colorado Weather: Partly Sunny, damp w/ some snow from prior storm.</p> <p>While there, I observed: Well(s): 2: Producing PR ; 1: Temporarily Abandoned TA. Battery: Active.</p> <p>Centralized Battery serves 1 Location ID (326701). (Well(s): 2: Producing PR ; 1: Temporarily Abandoned TA).</p> <p>Centralized Battery Formerly served 1 Location ID (326701). (Well(s): 1: Plugged & Abandoned PA).</p> <p>Centralized Battery serves 1 Tank Battery Facility ID (Pending).</p> <p>Reference: A.) Field Inspection Report doc. #707602155 and/or Location ID #326701 for PR, TA Well(s) info. B.) Field Inspection Report doc. #707602157 and/or Location ID #326701 for PA Well(s) info. C.) Field Inspection Report doc. #707602159 and/or Location ID #326701 for Battery / Facility, Equipment info.</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	12/02/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707602160	Site photo(s)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6341425