

Inspection Photos
Location Name: CAERUS PICEANCE LLC D13W Pad
Location ID: 334676



Photo # 7833 From entrance to location



Photo # 7834 From entrance to location

Inspection Photos

Location Name: CAERUS PICEANCE LLC D13W Pad

Location ID: 334676



Photo # 7835 Location



Photo # 7836 Location



Inspection Photos
Location Name: CAERUS PICEANCE LLC D13W Pad
Location ID: 334676



Photo # 7837 Location



Photo # 7838 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC D13W Pad
Location ID: 334676



Photo # 7839 Location



Photo # 7840 Tank label damaged & illegible

Inspection Photos
Location Name: CAERUS PICEANCE LLC D13W Pad
Location ID: 334676



Photo # 7841 Tank label damaged & illegible



Photo # 7842

Inspection Photos
Location Name: CAERUS PICEANCE LLC D13W Pad
Location ID: 334676



Photo # 7843 Hole in liner/liner needs maintenance



Photo # 7844 Hole in liner/liner needs maintenance