

# Inspection Photos

Loc: 472353

Operator: MCCOY PETROLEUM CORPORATION

Inspection Date: 11/29/2023

County: Kiowa



## Inspection Photos



**Photo 1.** Facing north along the access road. There are areas of the road where perennial vegetation has not established. This area of the road consists mostly of undesirable weeds.



## Inspection Photos



**Photo 2.** Facing north further along the access road. There are areas of the road where perennial vegetation has not established. This area of the road consists mostly of undesirable weeds.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:472353 | Date: 11/29/2023

## Inspection Photos



**Photo 3.** Facing north toward the fenced location.



## Inspection Photos



**Photo 4.** Facing northwest toward the fenced location. There are undesirable weed debris caught in the perimeter fence which will need to be removed.



## Inspection Photos



**Photo 5.** Southwest side of the location facing north. The brown vegetation is undesirable weeds of Russian thistle which will need to be controlled.



## Inspection Photos



**Photo 6.** Center of the location facing north. The lighter color vegetation is desirable grasses of Sand drop seed, Blue grama among other species.



## Inspection Photos



**Photo 7.** Center of the location facing west. The light colored vegetation is desirable grass but the darker vegetation further out is undesirable weeds.



## Inspection Photos



**Photo 8.** Facing toward the northwest portion of the location. The brown vegetation is undesirable weeds of Russian thistle.



## Inspection Photos



**Photo 9.** View of ground cover at areas of the location consisting of undesirable weeds of mostly Russian thistle.



## Inspection Photos



**Photo 10.** Facing west toward the surrounding undisturbed reference area which consists of native Blue grama, Sand dropseed, vegetation.

