

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/05/2023

Submitted Date:

12/05/2023

Document Number:

713300329**FIELD INSPECTION FORM**Loc ID 336404 Inspector Name: Kester, Michael On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1700 LINCOLN ST STE 4550City: DENVER State: CO Zip: 80203**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:10 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, KPK		cogcc@kpk.com	All Inspections
,		randy.silver@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241244	WELL	PR	12/01/2022	OW	123-09032	DACONO 1	PR
241246	WELL	PR	06/01/2023	OW	123-09034	DACONO 3	PR

General Comment:

LocationOverall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:	good		
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	
Corrective Action:	Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	PUMP JACK		
Comment:	safety guards		
Corrective Action:		Date:	
Type	LOCATION		
Comment:	chain link with wire		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Prime Mover	# 2		
Comment:	electric motors		
Corrective Action:		Date:	
Type: Pump Jack	#		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 2		
Comment:	pipd to surface		
Corrective Action:		Date:	
Type: Ancillary equipment	# 3		
Comment:	electrical disconnect panels		
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

--	--	--	--

Inspected Facilities

Facility ID: 241244 Type: WELL API Number: 123-09032 Status: PR Insp. Status: PR

Producing Well

Comment: PR, appeared to be shut in at time of inspection

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 05/11/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Facility ID: 241246 Type: WELL API Number: 123-09034 Status: PR Insp. Status: PR

Producing Well

Comment: PR, appeerd to be shut in at time of inspection

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 07/19/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

COGCC Comments

Comment

User

Date

Routine inspection

kestern

12/05/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713300330	site pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6345067