

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403569215

Date Received:

10/25/2023

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10665

Name of Operator: CCRP OPERATING INC

Address: 12136 W BAYAUD AVE STE 320

City: LAKEWOOD State: CO Zip: 80228

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Cody Duran

303-880-0790

cduran@rockiesresourcesllc.com

Jon Anderson

970-373-7397

janderson@rockiesresourcesllc.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 697504895

Inspection Date: 10/11/2023

FIR Submit Date: 10/17/2023

FIR Status: _____

Inspected Operator Information:

Company Name: CCRP OPERATING INC

Company Number: 10665

Address: 12136 W BAYAUD AVE STE 320

City: LAKEWOOD State: CO Zip: 80228

LOCATION - Location ID: 442375

Location Name: Cox Number: 22-B Pad County: _____

Qtrqr: NENW Sec: 22 Twp: 12N Range: 64W Meridian: 6

Latitude: 40.998623 Longitude: -104.535017

FACILITY - API Number: 05-123-00 Facility ID: 442375

Facility Name: Cox Number: 22-B Pad

Qtrqr: NENW Sec: 22 Twp: 12N Range: 64W Meridian: 6

Latitude: 40.998623 Longitude: -104.535017

CORRECTIVE ACTIONS:

1 ☒ CA# 185302

Corrective Action: Control and contain spills/releases, conduct maintenance on equipment and clean up per Rule 912.a.

Date: 10/11/2023

The corrective date is the date the location was observed out of compliance.

Response: CA COMPLETED

Date of Completion: 10/24/2023

Wellhead stained dirt was removed 10/19. Contaminated containment gravel was removed and replaced 10/24.

Operator
Comment:

COGCC Decision: Approved via an AMI

COGCC Representative: Approved via an AMI of this FIR resolution acknowledges the document and attachments were received. Based on the attached photos, Operator has completed the corrective action.

2 ☒ CA# 185303

Corrective Action: Comply with Rule 606.a.

Date: 10/11/2023

The corrective action date is the date the location was observed out of compliance.

Response: CA COMPLETED

Date of Completion: 10/19/2023

Operator
Comment:

Load out hoses removed and placed outside containment.

COGCC Decision: Approved via an AMI

COGCC Representative: Approved via an AMI of this FIR resolution acknowledges the document and attachments were received. Based on the attached photos, Operator has completed the corrective action.

OPERATOR COMMENT AND SUBMITTAL

Comment: Contaminated soil under wellhead was removed and replaced on 10/19. Load out hoses were disconnected and placed outside secondary containment. Removal of contaminated material inside containment commenced on 10/24.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Cody Duran

Signed: _____

Title: Production Engineer

Date: 10/25/2023 2:23:48 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403569215	FIR RESOLUTION SUBMITTED
403569407	Cox 5 wellhead after photo 10/19
403572842	Capped load out line
403572846	Cox 22 pad containment after photo
403572848	load out line outside containment and capped

Total Attach: 5 Files