

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/22/2023

Submitted Date:

11/29/2023

Document Number:

710500137

FIELD INSPECTION FORMLoc ID 484359 Inspector Name: Sanchez, Chris On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10797

Name of Operator: DESERT EAGLE OPERATING LLC

Address: 17101 PRESTON RD SUITE 105

City: DALLAS State: TX Zip: 75248

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

10 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Costa, Ryan		ryan.costa@state.co.us	
Bulf, Cathy		cathybulf@gmail.com	Desert Eagle Operating llc
Butler, Brad	972-345-9195	butleroil@yahoo.com	Desert Eagle Operating llc

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
484359	LOCATION	AC			-	Red Rocks 35-08	EI
484676	WELL	PR	09/29/2023	OW	071-09930	Red Rocks 35-08	EI

General Comment:

This is a follow-up Environmental Inspection for previous Environmental Inspection Document #710500010 for the Red Rocks 35-08 Location ID 4843359 Active well location Located in Las Animas County Colorado.

LocationOverall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

DEBRIS

Comment: There is a pile of trees stored on location.

Corrective Action: Comply with Rule 606

Date: 12/15/2023

Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities									
Facility ID:	<u>484359</u>	Type:	<u>LOCATION</u>	API Number:	<u>-</u>	Status:	<u>AC</u>	Insp. Status:	<u>EI</u>
Facility ID:	<u>484676</u>	Type:	<u>WELL</u>	API Number:	<u>071-09930</u>	Status:	<u>PR</u>	Insp. Status:	<u>EI</u>

Environmental**Waste Management:**

Type	Management	Condition	GPS (Lat) (Long)		
	Piles	Inadequate	37.471670	-103.539550	
Comment	There is a pile of unknown material adjacent to drill cuttings. Material appears to be scrapings from the location, which were originally impacted by drill cuttings material. The material should be managed in compliance with Rule 905 for E&P Waste Management				
Corrective Action	Comply with Rule 905.				Date: 12/15/2023
Drill Cuttings	Piles	Inadequate	37.471000	-104.539000	
Comment	Drill cuttings are not properly stored on location. Operator shall assure liner material is not permeable. Berm Material surrounding Drill Cuttings looks to be made up of Drill Cuttings material. Additionally, it appears the drill cuttings pile has been reduced in size since previous inspection. If the cuttings have been transported offsite, records will need to be provided to EPS Staff per Rule 905.b(3).				
Corrective Action	Magange and store Drill Cuttings in compliance with Rule 905				Date: 08/15/2023

Spill/Remediation:

Comment:	
Corrective Action:	Date: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

COGCC Comments

Comment	User	Date
Drill cuttings are not properly stored on location. Operator shall assure liner material is not permeable. Berm Material surrounding Drill Cuttings looks to be made up of Drill Cuttings material. Additionally, it appears the drill cuttings pile has been reduced in size since previous inspection. If the cuttings have been transported offsite, records will need to be provided to EPS Staff per Rule 905.b(3).	sanchezcc	11/29/2023
Original CA for Vehicle Rutting has been resolved	sanchezcc	11/29/2023
Original CA for Unused Equipment has been resolved	sanchezcc	11/29/2023
ECMC is requesting documentation showing the liner material used to store drill cutting is impermeable, Operator shall provide information for liner material by 12/15/2023	sanchezcc	11/29/2023

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403610321	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6338473
710500138	Location Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6338459