

Interim Reclamation and Stormwater Inspection

Date: 11/28/23

Operator: PDC Energy Inc. - 69175

Location ID: 329853

Inspection Document #: 713900139

Weld County, CO

Logan Hansen
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
 Location Name: Sanford 21-29 Pad
 Location ID: 329853



Colorado Energy & Carbon Management
 Commission
 Weld County
 +40.3754,-104.8035
 312° NW
 11/28/23, 9:51 AM



Colorado Energy & Carbon Management
 Commission
 Weld County
 +40.3752,-104.8047
 76° E
 11/28/23, 9:59 AM

Photo 1. The photo was taken at the entrance to the location facing Northwest. The photo illustrates the operator signage.

Photo 2. The photo was taken from the well location facing East. The photo illustrates the tertiary stormwater ditch surrounding the well location.

Inspection Photos
Location Name: Sanford 21-29 Pad
Location ID: 329853



Colorado Energy & Carbon Management
Commission
Weld County
+40.3753, -104.8049
350° N
11/28/23, 9:59 AM



Colorado Energy & Carbon Management
Commission
Weld County
+40.3752, -104.8039
354° N
11/28/23, 10:06 AM

Photo 3. The photo was taken from the well location facing North. The photo illustrates the western string of producing wells.

Photo 4. The photo was taken from the well location facing North. The photo illustrates the eastern string of producing wells.

Inspection Photos
Location Name: Sanford 21-29 Pad
Location ID: 329853



Photo 5. The photo was taken from the well location facing Northwest. The photo illustrates the tank signage needs replacing.



Photo 6. The photo was taken from the North end of the location facing Northeast. The photo illustrates a path being driven

Inspection Photos
Location Name: Sanford 21-29 Pad
Location ID: 329853



Photo 7. The photo was taken from the production facility facing Southwest. The photo illustrates improperly tracked slope.

Photo 8. The photo was taken from the production facility facing West. The photo illustrates runoff has creating erosion issues on the production pad.

Inspection Photos
Location Name: Sanford 21-29 Pad
Location ID: 329853



Photo 9. The photo was taken from the production facility facing East. The photo illustrates tumbleweeds growing in the ditch.