

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/28/2023

Submitted Date:

12/06/2023

Document Number:

713900139

FIELD INSPECTION FORM

Loc ID Inspector Name: On-Site Inspection ☐
 329853 Hansen, Logan 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 69175

Name of Operator: PDC ENERGY INC

Address: 1099 18TH STREET SUITE 1500

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

5 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogccinspection@pdce.com	
Binschus, Chris		chris.binschus@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
450827	LOCATION	AC	12/16/2022		-	IRISH PAD N/A	RI
452280	WELL	PR	06/01/2023	OW	123-45508	Sanford 30N-30B-M	RI
452281	WELL	PR	02/01/2020	OW	123-45509	Sanford 30C-30-M	RI
452282	WELL	PR	03/09/2020	OW	123-45510	Sanford 30N-30A-M	RI
452283	WELL	SI	07/01/2023	OW	123-45511	Sanford 4N-30C-M	RI
452316	WELL	PR	03/03/2020	OW	123-45532	Sanford 4N-30B-M	RI
452317	WELL	PR	02/01/2020	OW	123-45533	Sanford 4C-30-M	RI
452318	WELL	SI	01/01/2023	OW	123-45534	Sanford 4N-30A-M	RI
452355	WELL	PR	04/01/2022	OW	123-45545	Sanford 31N-30C-M	RI
463164	WELL	PR	06/01/2023	OW	123-49916	Sanford 03N	RI
463165	WELL	PR	07/01/2023	OW	123-49917	Sanford 32N-30C-M	RI
463167	WELL	PR	06/01/2022	OW	123-49919	Sanford 04NA	RI
463168	WELL	PR	06/01/2022	OW	123-49920	Sanford 10N	RI
463169	WELL	PR	06/01/2023	OW	123-49921	Sanford 01C	RI
463170	WELL	PR	07/01/2022	OW	123-49922	Sanford 12N	RI
463171	WELL	PR	02/13/2020	OW	123-49923	Sanford 5N-30B-M	RI
463172	WELL	PR	06/01/2022	OW	123-49924	Sanford 09N	RI
463173	WELL	PR	06/01/2022	OW	123-49925	Sanford 5C-30-M	RI
463174	WELL	PR	06/01/2022	OW	123-49926	Sanford 08C	RI
463176	WELL	PR	06/01/2022	OW	123-49928	Sanford 05N	RI
463177	WELL	PR	02/19/2020	OW	123-49929	Sanford 31N-30B-M	RI

463178	WELL	PR	06/01/2022	OW	123-49930	Sanford 32N-30B-M	RI
463179	WELL	SI	04/01/2023	OW	123-49931	Sanford 5N-30C-M	RI
463180	WELL	PR	06/01/2023	OW	123-49932	Sanford 02N	RI
463181	WELL	PR	06/01/2022	OW	123-49933	Sanford 07N	RI
463182	WELL	PR	06/01/2022	OW	123-49934	Sanford 11N	RI
463183	WELL	PR	06/01/2022	OW	123-49935	Sanford 06N	RI

General Comment:
[This is an Interim Reclamation and Stormwater Inspection.](#)

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	WEEDS		
Comment:	Weed debris in the form of tumbleweeds were observed in stormwater ditches and on the southern portion of the location. Tumbleweeds are a troublesome annual non-native weed that easily breaks off at the stem.		
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID: <u>450827</u>	Type: <u>LOCATION</u>	API Number: <u>-</u>	Status: <u>AC</u>	Insp. Status: <u>RI</u>
Facility ID: <u>452280</u>	Type: <u>WELL</u>	API Number: <u>123-45508</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>452281</u>	Type: <u>WELL</u>	API Number: <u>123-45509</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>452282</u>	Type: <u>WELL</u>	API Number: <u>123-45510</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>452283</u>	Type: <u>WELL</u>	API Number: <u>123-45511</u>	Status: <u>SI</u>	Insp. Status: <u>RI</u>
Facility ID: <u>452316</u>	Type: <u>WELL</u>	API Number: <u>123-45532</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>452317</u>	Type: <u>WELL</u>	API Number: <u>123-45533</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>452318</u>	Type: <u>WELL</u>	API Number: <u>123-45534</u>	Status: <u>SI</u>	Insp. Status: <u>RI</u>
Facility ID: <u>452355</u>	Type: <u>WELL</u>	API Number: <u>123-45545</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>463164</u>	Type: <u>WELL</u>	API Number: <u>123-49916</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>463165</u>	Type: <u>WELL</u>	API Number: <u>123-49917</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>463167</u>	Type: <u>WELL</u>	API Number: <u>123-49919</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>463168</u>	Type: <u>WELL</u>	API Number: <u>123-49920</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>463169</u>	Type: <u>WELL</u>	API Number: <u>123-49921</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>463170</u>	Type: <u>WELL</u>	API Number: <u>123-49922</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>463171</u>	Type: <u>WELL</u>	API Number: <u>123-49923</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>463172</u>	Type: <u>WELL</u>	API Number: <u>123-49924</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>463173</u>	Type: <u>WELL</u>	API Number: <u>123-49925</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>463174</u>	Type: <u>WELL</u>	API Number: <u>123-49926</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>

Inspector Name: Hansen, Logan

Facility ID:	463176	Type:	WELL	API Number:	123-49928	Status:	PR	Insp. Status:	RI
Facility ID:	463177	Type:	WELL	API Number:	123-49929	Status:	PR	Insp. Status:	RI
Facility ID:	463178	Type:	WELL	API Number:	123-49930	Status:	PR	Insp. Status:	RI
Facility ID:	463179	Type:	WELL	API Number:	123-49931	Status:	SI	Insp. Status:	RI
Facility ID:	463180	Type:	WELL	API Number:	123-49932	Status:	PR	Insp. Status:	RI
Facility ID:	463181	Type:	WELL	API Number:	123-49933	Status:	PR	Insp. Status:	RI
Facility ID:	463182	Type:	WELL	API Number:	123-49934	Status:	PR	Insp. Status:	RI
Facility ID:	463183	Type:	WELL	API Number:	123-49935	Status:	PR	Insp. Status:	RI

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: IRRIGATED

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: IRRIGATED

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads _____ Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: Corrective Action:

Date _____

Overall Final Reclamation _____

Well Release on Active Location ☐Multi-Well Location ☐**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: The production facility has been tracked improperly along the East side of the pad and has lead to erosion off of the pad. The operator shall ensure the slope is properly stabilized.Reference inspection photos for detials.Corrective Action: Install or fix required BMP's per Rule 1002.f. in accordance with good engineering practices.

Date: 11/28/2023

Pits: ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713900155	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6347100