

Inspection Photos

12/05/2023

Operator: TEP ROCKY MOUNTAIN LLC #96850
/ NONSUCH NATURAL GAS INC #10163

Location ID: 322524 (TEP), 453726 (Nonsuch)

Inspection Doc: 696205436

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850 / NONSUCH NATURAL GAS INC #10163

Location ID: 322524 (TEP), 453726 (Nonsuch)



Photo 1: Photos 1-2 taken from the east end of the Location. Photos provide an overview from south, southwest, northwest to north.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850 / NONSUCH NATURAL GAS INC #10163

Location ID: 322524 (TEP), 453726 (Nonsuch)



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850 / NONSUCH NATURAL GAS INC #10163

Location ID: 322524 (TEP), 453726 (Nonsuch)



December 5, 2023

Photo 3: Equipment from Nonsuch's Tank Battery facility remains on the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850 / NONSUCH NATURAL GAS INC #10163

Location ID: 322524 (TEP), 453726 (Nonsuch)



Photo 4: Additional contour work appears to have been conducted at the Location entrance.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850 / NONSUCH NATURAL GAS INC #10163

Location ID: 322524 (TEP), 453726 (Nonsuch)



Photo 5: Hydromulch applied to slopes.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850 / NONSUCH NATURAL GAS INC #10163

Location ID: 322524 (TEP), 453726 (Nonsuch)



Photo 6: Photos taken from along the access road. Photo right example showing erosion degradation (rill/gully erosion) along the access road documented in prior inspections remains apparent and have not been addressed.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources