

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/05/2023

Submitted Date:

12/06/2023

Document Number:

705000538**FIELD INSPECTION FORM**Loc ID 321307 Inspector Name: Maclaren, Joe On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10459Name of Operator: EXTRACTION OIL & GAS INCAddress: 555 17TH STREET SUITE 3700City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		Inspections@civiresources.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
206632	WELL	SI	07/01/2023	OW	013-06127	ERIE 1-24	PA
321307	LOCATION	AC			-	ERIE-61N69W 24SENW	EG

General Comment:ECMC Engineering Integrity Inspection; Flowline Inspection
Photos uploaded

Inspected Facilities

Facility ID: 206632 Type: WELL API Number: 013-06127 Status: SI Insp. Status: PA

Flowline

#1	Type: Non-Well Site	of Lines	
----	---------------------	----------	--

Flowline Description

Flowline Type: Non-Well Site Size: 2" Material: Carbon Steel
 Variance: Age: Contents:

Integrity Summary

Failures: Spills: Repairs Made:
 Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules (check all that apply)

☐ 1101. Installation and Reclamation ☐ 1102. Operations, Maintenance, and Repair ☐ 1103. Abandonment

Comment: Well is plugged and abandoned (Erie 1-24); ECMC form 42 notice of start of plugging operations doc #403536525 received on 09/20/2023. The OLF wellhead flowline/ riser has been removed. The facility/ tank battery has been decommissioned; tanks and equipment removed. Fenced excavations observed at PA well and facility/ battery areas. No flowlines/ or risers observed. Excavation/ remediation work is in progress.

Corrective Action:

Date:

Facility ID: 321307 Type: LOCATION API Number: - Status: AC Insp. Status: EG

COGCC Comments

Comment	User	Date
As outlined on COGCC form 19 spill report Doc #403602656 received on 11/21/2023: During facility decommissioning activities, audio, visual, and olfactory measures indicated a potential historical release. Lease operators are coached to conduct routine AVO inspections on all oil and gas facilities.	maclarej	12/06/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
705000541	View of location; WH & facility excavations	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6347822
705000542	Excavation at PA well; view E to facility/ excavation	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6347823