

Inspection Photos

Location Name: CAERUS PICEANCE LLC, NPR/K10-596

Location ID: 335676

Date: 12/4/2023



Location Entrance – Photo #07824



West End of Location – Photo #07825

Inspection Photos

Location Name: CAERUS PICEANCE LLC, NPR/K10-596

Location ID: 335676

Date: 12/4/2023



Wellheads – Photo #07828



Gas Meters – Photo #07827

Inspection Photos

Location Name: CAERUS PICEANCE LLC, NPR/K10-596

Location ID: 335676

Date: 12/4/2023



Tank Battery – Photo #07831



Mobile Separator – Photo #07830

Inspection Photos

Location Name: CAERUS PICEANCE LLC, NPR/K10-596

Location ID: 335676

Date: 12/4/2023



Lack of Stabilization – Photo #07834



Lack of Stabilization/Sediment Transport of Sediment – Photo #07833

Inspection Photos

Location Name: CAERUS PICEANCE LLC, NPR/K10-596

Location ID: 335676

Date: 12/4/2023



Insufficient Vehicle Tracking BMPs at Location Entrance/Exit
– Photo #07835