

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/29/2023

Submitted Date:

11/30/2023

Document Number:

713600430

FIELD INSPECTION FORM

Loc ID 324840 Inspector Name: COSTA, RYAN On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 83130
Name of Operator: STRACHAN EXPLORATION INC
Address: 383 INVERNESS PKWY, STE 360
City: ENGLEWOOD State: CO Zip: 80112

Findings:

- 6 Number of Comments
- 5 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
BEAR STACY		stacy@strachanexploration.com	
HARMS JASON		jason@strachanexploration.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
213042	WELL	PR	09/24/2007	OW	061-06403	WEINMAN 1-27	RI

General Comment:

This is a follow up of the previous inspection #713600140.
See attached photos and additional details within this report

Location

Overall Good:

Signs/Marker:

Type	BATTERY		
Comment:	The tank battery sign is faded and does not meet the signage requirements of Rule 605.e. Previous corrective action is not completed.		
Corrective Action:	Install sign to comply with Rule 605.e.	Date:	08/24/2023
Type	WELLHEAD		
Comment:	The well sign is faded and does not meet the signage requirements. Previous corrective action is not completed.		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	05/13/2023

Emergency Contact Number:

Comment:	<input type="text"/>	
Corrective Action:	<input type="text"/>	Date: <input type="text"/>

Overall Good:

Spills:

Type	Area	Volume		
Crude Oil	Tank			
Comment:	There is oil stained soil behind (west side) the tank.			
Corrective Action:	Clean up per Rule 912.a.	Date:	11/29/2023	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	LOCATION		
Comment:	The fence around the tanks and production equipment is inadequate to prevent livestock entry and is not maintained. Previous corrective action is not completed.		
Corrective Action:	Comply with the fencing requirements per the 1002a rules.	Date:	08/24/2023

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
	3		STEEL AST		
Comment:	<input type="text"/>				
Corrective Action:	<input type="text"/>				Date: <input type="text"/>

Paint

Condition	<input type="text"/>
Other (Content)	<input type="text"/>
Other (Capacity)	<input type="text"/>
Other (Type)	<input type="text"/>

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient	Base Insufficient	Inadequate

Comment:	The berm around the tank battery is insufficient to contain a spill. Berms need to be compacted and built to be impermeable. Previous corrective action is not completed.	
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 603.o.	Date: 08/24/2023

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403611712	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6339913
713600431	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6339879