

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input style="width: 95%;" type="text"/>		
Corrective Action:	<input style="width: 95%;" type="text"/>	Date:	<input style="width: 80%;" type="text"/>

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Equipment:

				corrective date
Type: Plunger Lift	# 0			
Comment:				
Corrective Action:		Date:		

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 250989 Type: WELL API Number: 123-18792 Status: TA Insp. Status: PA

COGCC Comments

Comment	User	Date
Well has been plugged, night cap installed and is awaiting casing cut and cap. Flow line remains at well head at time of inspection. Former battery remaining serving active wells.	carlilec	12/07/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690011931	Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6348645