



PHOTO 1: THE OILY FLUIDS HAVE BEEN REMOVED FROM THE ENGINE SKID AND MAINTENANCE HAS BEEN CONDUCTED ON ALL EQUIPMENT. THE IMPACTED SOIL HAS BEEN REMOVED AND REPLACED WITH FRESH GRAVEL MATERIAL. THE SELF INSPECTION PROCESS HAS BEEN REVIEWED.