

# Inspection Photos

Loc: 308613

Operator: OGRIS OPERATING LLC

Inspection Date: 12/5/2023

County: LAS ANIMAS



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing northwest along the access road which is stabilized with vegetation and gravel. Culvert outlet protection is installed at the culvert outlet.



## Inspection Photos



**Photo 2.** Facing west toward the wellsite.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:308613 | Date: 12/5/2023

## Inspection Photos



**Photo 3.** There are some parts laying on the back side of the engine that should be removed.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:308613 | Date: 12/5/2023

## Inspection Photos



**Photo 4.** There is stained soil next to the engine skid that will need to be cleaned up.

