

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/30/2023

Submitted Date:

12/01/2023

Document Number:

707602135

FIELD INSPECTION FORM

Loc ID 310599	Inspector Name: Evins, Bret	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 11 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
Operator Information: OGCC Operator Number: 100322 Name of Operator: NOBLE ENERGY INC Address: 2001 16TH STREET SUITE 900 City: DENVER State: CO Zip: 80202				
ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE				

Contact Information:			
Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Inspections

Inspected Facilities:							
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
293966	WELL	TA	11/19/2021	OW	123-26657	TREBOR B 11-25	TA

General Comment: <p>This is a WELL inspection. Well(s): 1: Temporarily Abandoned TA. Battery: Inactive Shut-down.</p> <p>Centralized Battery serves 1 Location ID (310599). (Well(s): 1: Temporarily Abandoned TA).</p> <p>Centralized Battery Formerly served 2 Location IDs (323725, 326893). (Well(s): 2: Plugged & Abandoned PA).</p> <p>Centralized Battery serves 1 Tank Battery Facility ID (Pending).</p> <p>Reference: A.) Field Inspection Report doc. #707602135 and/or Location ID #310599 for TA Well(s) info. B.) Field Inspection Report doc. #707602137 and/or Location ID #323725 for PA Well(s) info. C.) Field Inspection Report doc. #707602139 and/or Location ID #326893 for PA Well(s) info. D.) Field Inspection Report doc. #707602141 and/or Location ID #310599 for Battery / Facility, Equipment info.</p>
--

Location				
Lease Road:				
Type	Access			
comment:	Adequate			
Corrective Action	L		Date:	
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:				
Corrective Action:			Date:	
Emergency Contact Number:				
Comment:				
Corrective Action:				Date: _____
Good Housekeeping:				
Type	WEEDS			
Comment:	Overgrown vegetation at wellsite. Refer to Rule 606.c for guidance.			
Corrective Action:	*Remove, manage, & control overgrown vegetation around wellsite. Comply with Rule 606.c. Corrective Action date: 01/02/2024. (30-days). See photo #1. *Please attach photo(s) to FIRR to verify Corrective Action(s) have been resolved.		Date:	01/02/2024
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	WELLHEAD			
Comment:	Iron panel.			
Corrective Action:			Date:	
Equipment:				
Type: Plunger Lift	# 0			corrective date
Comment:	Temporarily Abandoned TA, Equipment removed.			
Corrective Action:			Date:	
Type: Other	# 1			
Comment:	Wellhead: w/ Master, casing valves.			
Corrective Action:			Date:	
Type: Bradenhead	# 1			
Comment:	Appears plumbed to surface.			
Corrective Action:			Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
			CENTRALIZED BATTERY		40.408743,-104.517790	
Comment:	Centralized Battery serves 1 Location ID (310599). (Well(s): 1: Temporarily Abandoned TA). Centralized Battery serves 1 Tank Battery Facility ID (Pending).					
Corrective Action:					Date:	

Paint

Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected FacilitiesFacility ID: 293966 Type: WELL API Number: 123-26657 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Temporarily Abandoned | TA.
Disconnected from flowline.
Battery: Inactive | Shut-down.
Locked-Out, Tagged-Out | LOTO.
Blue TA tag posted.
CECMC records last production: 04/2020.

Form 4 on file. TA date: 11/04/2021. Approved.
DH-CIBP set.
Form 21 MIT on file. MIT date: 11/08/2021. Approved.
Form 6A on file. Out-of-Svc Designation.
Date: 02/16/2020. Approved.

Corrective Action: Date: **BradenHead**Date of Last Brhd Test: 04/09/2023 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: End Surf Csg Pressure: 0Comment: Corrective Action: Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment:

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>CECMC Inspection Report Summary:</p> <p>On THU 11/30/2023 at approximately 13:52 hrs. I, Bret Evins, conducted an onsite inspection at: Operator Name: NOBLE ENERGY INC Location Name: TREBOR B-65N64W/11NESW Location ID: 310599 Well Name(s): Trebor B 11-25. API: 123-26657. Location County: Weld County, Colorado Weather: Partly Sunny, damp w/ some snow from prior storm.</p> <p>While there, I observed: Well(s): 1: Temporarily Abandoned TA. Battery: Inactive Shut-down.</p> <p>Centralized Battery serves 1 Location ID (310599). (Well(s): 1: Temporarily Abandoned TA).</p> <p>Centralized Battery Formerly served 2 Location IDs (323725, 326893). (Well(s): 2: Plugged & Abandoned PA).</p> <p>Centralized Battery serves 1 Tank Battery Facility ID (Pending).</p> <p>Reference: A.) Field Inspection Report doc. #707602135 and/or Location ID #310599 for TA Well(s) info. B.) Field Inspection Report doc. #707602137 and/or Location ID #323725 for PA Well(s) info. C.) Field Inspection Report doc. #707602139 and/or Location ID #326893 for PA Well(s) info. D.) Field Inspection Report doc. #707602141 and/or Location ID #310599 for Battery / Facility, Equipment info.</p> <p>During this inspection the following possible compliance issue(s) were observed: 1.) Overgrown vegetation at wellsite. Refer to Rule 606.c for guidance. *Remove, manage, & control overgrown vegetation around wellsite. Comply with Rule 606.c. Corrective Action date: 01/02/2024. (30-days). See photo #1.</p> <p>*Please attach photo(s) to FIRR to verify Corrective Action(s) have been resolved.</p> <p>*A follow up on this site inspection will be conducted to ensure that compliance issues have been corrected to comply with CECMC rules.</p> <p>This is a summary of the inspection report.</p>	evinsb	12/01/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403612755	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6341196
707602136	Site photo(s)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6341173