

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/06/2023

Submitted Date:

12/07/2023

Document Number:

696305477

**FIELD INSPECTION FORM**Loc ID 440840 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 8960

Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY

Address: 555 17TH STREET SUITE 3700

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

14 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		Inspections@civiresources.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
440839	WELL	SI	06/01/2023	OW	123-41147	State Antelope J-1-36XRLNB	SI
440841	WELL	SI	06/01/2023	OW	123-41148	State Antelope J14-1-36XRLNC	SI
440842	WELL	PR	08/01/2023	OW	123-41149	State Antelope J24-1-36XRLNC	PR
440843	WELL	PR	08/01/2023	OW	123-41150	State Antelope O24-1-36XRLNC	PR
440844	WELL	SI	08/01/2023	OW	123-41151	State Antelope 24-1-36XRLNB	SI

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	OTHER		
Comment:	Risers at Tanks are Disconnected flowline risers not OOSLAT. See photos		
Corrective Action:	Complete flowline and crude oil transfer line abandonments to comply with Rule 1105.	Date:	12/22/2023
Type	TRASH		
Comment:	Locate Tags on Location no longer in use or valid. See photos		
Corrective Action:	Comply with Rule 606	Date:	12/22/2023
Type	UNUSED EQUIPMENT		
Comment:	Unused Chemical Containter inside Tank Berm. See photos		
Corrective Action:	Comply with Rule 606	Date:	12/22/2023

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Panels		
Corrective Action:		Date:	
Type	LOCATION		
Comment:	Barbed Wire		
Corrective Action:		Date:	

**Equipment:**

Type: Bradenhead	# 5		corrective date
Comment:			
Corrective Action:		Date:	

Type: Plunger Lift	# 5		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 10		
Comment:			
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Instrumental Air Unit		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 5		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	500 BBLs	STEEL AST		40.423350,-104.276210	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
			Date:	

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		
		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	
	Date:

**Inspected Facilities**Facility ID: 440839 Type: WELL API Number: 123-41147 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_Comment: SI

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 440841 Type: WELL API Number: 123-41148 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_Comment: SI

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 440842 Type: WELL API Number: 123-41149 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 440843 Type: WELL API Number: 123-41150 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 440844 Type: WELL API Number: 123-41151 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_Comment: SI

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<a href="#">Routine Field Inspection. Locate Tags on Location no longer in use or valid. Unmarked Risers at Tank Riser. Unused Red Chemical Tank inside Tank Berm</a>	petrie	12/07/2023

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696305478	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6349940">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6349940</a>