

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/07/2023

Submitted Date:

12/08/2023

Document Number:

705000545

FIELD INSPECTION FORM

Loc ID 318489 Inspector Name: Maclaren, Joe On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

Findings:

- 3 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		ECMCInspections@Oxy.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241397	WELL	TA	09/01/2023	OW	123-09186	ALBERT D. KURTZ GAS UNIT "C" 1	PA
446316	TANK BATTERY	AC	06/22/2016		-	ALBERT D KURTZ GAS UNIT C-63N67W 21NESW	EG

General Comment:

ECMC Engineering Integrity Inspection; Flowline Inspection
Photos uploaded

Inspected Facilities

Facility ID: 241397 Type: WELL API Number: 123-09186 Status: TA Insp. Status: PA

Flowline

#1	Type: Well Site	of Lines
----	-----------------	----------

Flowline Description

Flowline Type: Well Site Size: 2" Material: Carbon Steel
 Variance: Age: Contents:

Integrity Summary

Failures: Spills: Repairs Made:
 Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules (check all that apply)

1101. Installation and Reclamation 1102. Operations, Maintenance, and Repair 1103. Abandonment

Comment: Well (Albert Kurtz GU 1) has been plugged and abandoned. ECMC form 42 notice of start of plugging operations doc #403605057 received on 08/11/2023. Fenced excavation observed at the PA wellhead; flowline riser (WH) at PA well has been cut, bullplugged below grade. An open excavation at facility/ battery inlet to HHS exposed the second end of the flowline (cut, bullplugged below grade). The wellhead OLF flowline is currently AIP. Facility/ battery services additional (SI) wells. Remediation is in progress (historical).

Corrective Action:

Date:

Facility ID: 446316 Type: TANK API Number: - Status: AC Insp. Status: EG

COGCC Comments

Comment	User	Date
As outlined on COGCC form 19 spill report Doc #403605057 received on 11/22/2023: On November 22, 2023, historically impacted soil was discovered following cut and cap operations at the Kurtz Albert D GU C 1 wellhead location. Excavation and assessment activities are ongoing. Site infrastructure has been removed and will not be replaced.	maclarej	12/08/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
705000546	Fence excavation at PA well; OL WH FL AIP	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6350500
705000547	Flowline excavations at HHS; AIP (end marked)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6350501