

Interim Reclamation and Stormwater Inspection

Date: 12/06/2023

Operator: NOBLE ENERGY INC - 100322

Location ID: 421834

Inspection Document #: 708200743

Weld County, CO

Dylan Edwardson
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Igo Creek 09-13H
Location ID: 421834



Photo 1. Broken load out line/hose observed within tank battery secondary containment.

Inspection Photos
Location Name: Igo Creek 09-13H
Location ID: 421834



Photo 2. Stained soil observed near secondary containment.

Inspection Photos
Location Name: Igo Creek 09-13H
Location ID: 421834



Photo 3. No wildlife exclusion device (e.g. netting) observed around secondary containment at methanol tank.

Inspection Photos
Location Name: Igo Creek 09-13H
Location ID: 421834



Photo 4. Northern portion of the location, within the interim areas. Appears interim reclamation activities have been performed to reduce disturbance areas only needed for production operations. Vegetation throughout the interim areas is progressing towards Rule 1003 standards and will need to be re-inspected during the next growing season to verify vegetative compliance; therefore, the location will remain IN-PROCESS. Operator shall continue to monitor and manage this site until the location meets Rule 1003 standards, including stormwater and weed management.

Inspection Photos
Location Name: Igo Creek 09-13H
Location ID: 421834



Photo 5. Taken from the northwest portion of the interim area. See comments in Photo 4.

Inspection Photos
Location Name: Igo Creek 09-13H
Location ID: 421834



Photo 6. Taken from the western portion of the production areas. See comments in Photo 4.