

Interim Reclamation and Stormwater Inspection

Date: 12/06/2023

Operator: NOBLE ENERGY INC - 100322

Location ID: 431581

Inspection Document #: 708200747

Weld County, CO

Dylan Edwardson
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos

Location Name: Timbro LC13-75-1HN Pad

Location ID: 431581



Photo 1. Cattle panel located on the east side of the production areas does not appear to be in use.

Inspection Photos

Location Name: Timbro LC13-75-1HN Pad

Location ID: 431581



Photo 2. Unused equipment observed on the south side of the production areas.

Inspection Photos

Location Name: Timbro LC13-75-1HN Pad

Location ID: 431581




Photo 3. Stained soil observed near wellhead.

Inspection Photos
Location Name: Timbro LC13-75-1HN Pad
Location ID: 431581



Photo 4. Stained soil observed underneath tank.

Inspection Photos

Location Name: Timbro LC13-75-1HN Pad

Location ID: 431581



Photo 5. Earthen berms/secondary containment does not appear to be adequate to contain 150% of tank volume and requires repair/replacement.

Inspection Photos
Location Name: Timbro LC13-75-1HN Pad
Location ID: 431581



Photo 6. Southern portions of the interim areas are experiencing non-uniform vegetation cover resulting in bare soil and undesirable vegetation (e.g. russian thistle). Additional reclamation activities are required to stabilize the bare soil.

Inspection Photos
Location Name: Timbro LC13-75-1HN Pad
Location ID: 431581



Photo 7. Continued from Photo 6, facing east.