

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type WELLHEAD

Comment: red ag fencing

Corrective Action:

Date: _____

Equipment:

corrective date

Type: Gas Meter Run

1

Comment:

Corrective Action:

Date: _____

Type: Bird Protectors

1

Comment:

Corrective Action:

Date: _____

Type: Ancillary equipment

1

Comment: automation

Corrective Action:

Date: _____

Type: Horizontal Heated Separator

1

Comment:

Corrective Action:

Date: _____

Type: Plunger Lift

1

Comment:

Corrective Action:

Date: _____

Type: Bradenhead

1

Comment: plumbed to surface

Corrective Action:

Date: _____

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLS	Open Top		,
Comment: <input type="text"/>					
Corrective Action: <input type="text"/>					Date: _____

Paint	
Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	shares containment with oil tank			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	LVST		
Comment:					
Corrective Action:					Date:

Paint	
Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:	
Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 202869 Type: WELL API Number: 001-08274 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 10/26/2022 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
At time of inspection location appears to be in compliance with ECMC rules. At time of inspection weather conditions were cold, calm, clear.	medinaj	12/05/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699505180	inspection pictures	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6351194