

Location

Overall Good:

Signs/Marker:			
Type	DRILLING/RECOMP		
Comment:	adequate		
Corrective Action:			Date:

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type			
Comment:			
Corrective Action:			Date:

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 247505 Type: WELL API Number: 123-15302 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: SI, Form 42(MIRU) Doc # 403611361 & Form 42 (PA) Doc # 403611391.

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 10/26/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 7 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____ Date: _____

Workover

Comment: Axis WO Rig 721 on location getting RU & pumping water to KTW before PA operations start.

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>ECMC Inspection Report Summary On Friday 12-8-2023 at approximately 1330 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection: Form 42 (MIRU) Doc # 403611361 and Form 42 (PA) Doc # 403 611391. Operator: Oxy/Kerr McGee Location name: Location ID # 327907 Well Name: Asbury Gas Unit 1. API # 05-123-15302. County: Weld Weather: Cloudy, cold. Location: Dry. While there, I observed a well site, SI with active workover/PA operations at the time of the inspection. During this inspection, I observed no compliance issues: See attached photos. I spoke with Luis Morales Oxy WS Supervisor and he informed me they were just getting RU & pumping water downhole to KTW. No follow up site inspection is needed to ensure that the addressed Compliance issues comply with ECMC rules.</p>	revasr	12/08/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702402587	location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6351213