

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/05/2023

Submitted Date:

12/08/2023

Document Number:

707602177

**FIELD INSPECTION FORM**Loc ID 306224 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 2001 16TH STREET SUITE 900

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

12 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
306224	LOCATION	AC			-	MILE-HI SHEEP-66N64W 8SWSW	AO

**General Comment:**

This is a BATTERY inspection.  
Well(s): 2: Producing | PR.  
Battery: Active.

Centralized Battery serves 2 Location IDs  
(306224, 305762).  
(Well(s): 2: Producing | PR).

Centralized Battery formerly served 1 Location ID  
(305545).  
(Well(s): 1: Plugged & Abandoned | PA).

Centralized Battery serves 1 Tank Battery Facility ID  
(Pending).

Reference:  
A.) Field Inspection Report doc. #707602173 and/or Location ID #306224  
for PR Well(s) info.  
B.) Field Inspection Report doc. #707602175 and/or Location ID #305762  
for PR Well(s) info.  
C.) Field Inspection Report doc. #707602177 and/or Location ID #306224  
for Battery / Facility, Equipment info.  
D.) Field Inspection Report doc. #698705397 and/or Location ID #305762  
for Current Corrective Actions info.

Location				
<b>Lease Road:</b>				
Type	Access			
comment:	Adequate			
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
<b>Signs/Marker:</b>				
Type	TANK LABELS/PLACARDS			
Comment:				
Corrective Action:				Date:
Type	BATTERY			
Comment:				
Corrective Action:				Date:
Emergency Contact Number:				
Comment:				
Corrective Action:				Date: _____
Overall Good: <input type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Fencing/:</b>				
Type	SEPARATOR			
Comment:	Surrounded by metal berms.			
Corrective Action:				Date:
<b>Equipment:</b>				
				corrective date
Type: Gas Meter Run	# 1			
Comment:	1: Gas Sales: Calibration card(s) indicates calibration <= 1 year. Last calibration: 08/10/2023. Inactive, NO production.			
Corrective Action:				Date:
Type: Emission Control Device	# 2			
Comment:	1: Crude storage vapor line combustor(s). Controls crude oil tank(s) vapors. Pilots: ON. 1: Separator vapor line combustor(s). Controls separator(s) vapors. Pilots: ON.			
Corrective Action:				Date:
Type: Bird Protectors	# 4			
Comment:				
Corrective Action:				Date:
Type: Pig Station	# 1			

Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 2		
Comment: Battery site. ECD scrubber(s).			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		,
Comment: Centralized Battery serves 2 Location IDs (306224, 305762). (Well(s): 2: Producing   PR).  Centralized Battery serves 1 Tank Battery Facility ID (Pending).					
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLS	CONCRETE SUMP/VAULT		,
Comment:					
Corrective Action:				Date:	

**Paint**

Condition	
Other (Content)	
Other (Capacity)	35 Bbls.
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficient	Adequate
Comment: Berms shared w/ crude oil tank(s), produced H2O vault(s).				

Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	2	OTHER	STEEL AST		40.496587,-104.581834	
Comment: Equalizer line(s) connect crude oil tank(s).						
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	250 Bbls.	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment: Berms shared w/ crude oil tank(s), produced H2O vault(s).					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:	Date:		

Flaring:

Type			
Comment:			
Corrective Action:	Date:		



**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p><b>CECMC Inspection Report Summary:</b></p> <p>On TUE 12/05/2023 at approximately 16:24 hrs. I, Bret Evins, conducted an onsite inspection at:  Operator Name: NOBLE ENERGY INC  Location Name: MILE-HI SHEEP-66N64W/8SWSW  Location ID: 306224  Well Name(s):  Mile-Hi Sheep 8-35, Mile High Sheep 8-32.  API:  123-24252, 123-23451.  Location County: Weld County, Colorado  Weather: Partly Sunny, damp from prior storm.</p> <p>While there, I observed:  Well(s): 2: Producing   PR.  Battery: Active.</p> <p>Centralized Battery serves 2 Location IDs (306224, 305762).  (Well(s): 2: Producing   PR).</p> <p>Centralized Battery formerly served 1 Location ID (305545).  (Well(s): 1: Plugged &amp; Abandoned   PA).</p> <p>Centralized Battery serves 1 Tank Battery Facility ID (Pending).</p> <p>Reference:  A.) Field Inspection Report doc. #707602173 and/or Location ID #306224 for PR Well(s) info.  B.) Field Inspection Report doc. #707602175 and/or Location ID #305762 for PR Well(s) info.  C.) Field Inspection Report doc. #707602177 and/or Location ID #306224 for Battery / Facility, Equipment info.  D.) Field Inspection Report doc. #698705397 and/or Location ID #305762 for Current Corrective Actions info.</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	12/08/2023

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
707602178	Site photo(s)	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6351217">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6351217</a>