

Inspection Photos

Location Name: CAERUS PICEANCE LLC BATTLEMENT MESA 27-44 (27P) Pad

Location ID: 334317



Photo # 8877 From entrance to location




Photo # 8878 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC BATTLEMENT MESA 27-44 (27P) Pad

Location ID: 334317



Photo # 8879 Location



Photo # 8880 Location



Inspection Photos

Location Name: CAERUS PICEANCE LLC BATTLEMENT MESA 27-44 (27P) Pad

Location ID: 334317



Photo # 8881 Location



Photo # 8882 Location



Inspection Photos

Location Name: CAERUS PICEANCE LLC BATTLEMENT MESA 27-44 (27P) Pad

Location ID: 334317



Photo # 8883 Methanol tank improperly labeled/lacks required information



Photo # 8884 Methanol tank improperly labeled/lacks required information



Inspection Photos

Location Name: CAERUS PICEANCE LLC BATTLEMENT MESA 27-44 (27P) Pad

Location ID: 334317



Photo # 8885 Methanol tank



Photo # 8886 PRV vent line lacks cap

Inspection Photos

Location Name: CAERUS PICEANCE LLC BATTLEMENT MESA 27-44 (27P) Pad

Location ID: 334317



Photo # 8887 PRV vent line lacks cap



Photo # 8888 Debris

Inspection Photos

Location Name: CAERUS PICEANCE LLC BATTLEMENT MESA 27-44 (27P) Pad

Location ID: 334317



Photo # 8889 Debris