

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/06/2023

Submitted Date:

12/08/2023

Document Number:

707602163

**FIELD INSPECTION FORM**

Loc ID 306349 Inspector Name: Evins, Bret On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 100322  
Name of Operator: NOBLE ENERGY INC  
Address: 2001 16TH STREET SUITE 900  
City: DENVER State: CO Zip: 80202

**Findings:**

6 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
288024	WELL	PR	08/24/2023	OW	123-24495	HOWARD USX A 9-10	PA

**General Comment:**

This is a **PLUGGED & ABANDONED WELL** inspection.  
Well(s): 1: Plugged & Abandoned | PA.  
Plugging Operations: Cementing; Cement-surface.  
Battery: Active.  
Active Battery SE corner GPS coordinates: 40.496656 / -104.550730  
Well GPS coordinates: 40.498780 / -104.552830

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Adequate		
Corrective Action:		Date:	

Overall Good:

<b>Signs/Marker:</b>			
Type	OTHER		
Comment:	Jobsite entrance & safety signage posted.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

<b>Emergency Contact Number:</b>			
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>	Date:	<input type="text"/>

Overall Good:

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Venting:</b>			
Yes/No			
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 288024 Type: WELL API Number: 123-24495 Status: PR Insp. Status: PA

**Cement**

Cement Contractor

Contractor Name: A-Plus Well

Contractor Phone: \_\_\_\_\_

Surface Casing

Cement Volume (sx): \_\_\_\_\_

Circulate to Surface: \_\_\_\_\_

Cement Fall Back: \_\_\_\_\_

Top Job, 1" Volume: \_\_\_\_\_

Intermediate Casing

Cement Volume (sxs): \_\_\_\_\_

Good Return During Job: \_\_\_\_\_

Production Casing

Cement Volume (sx): \_\_\_\_\_

Good Return During Job: \_\_\_\_\_

Plugging Operations

Depth Plugs(feet range): 788'-0'

Cement Volume (sx): 302 sxs

Good Return During Job: \_\_\_\_\_

Cement Type: Class "G" Neat 15.8#

Comment:

Workover Contractor: A-Plus Well Services, Rig #12.  
 Cement Contractor: A-Plus Well Services.

Reference:  
 Form 6N on file. Notice of Intent to Abandon date: 08/25/2023. Approved.  
 Form 42 on file. Notice of MIRU. Start Date: 12/05/2023. Approved.  
 Form 42 on file. Notice of Plugging Operations. Start Date: 12/05/2023. Approved.

2023/12/06:  
 Plugging Operations: Cementing; Cement-surface.  
 2023/12/06: JSA attached as photo to this report.

Safety JSA Meeting SWC/SYLA, LOCK/OUT TAG OUT. START EQUIPMENT.  
 CHECKGROUNDING (WSEA 2-A)  
 CHECK PSI. CSG O PSI. SURFACE O PSI  
 OPEN WELL TO TANK, FLOW CHECK 15 MIN. WELL STATIC (WSEA 10-A)  
 CONDITION HOLE W/10 BBLS CHEM WASH & 60 BBLS FRESH WATER  
 OPEN WELL TO TANK. FLOW CHECK 15 MIN. WELL STATIC (WSEA10-Bi  
 TEST PUMP LINES. PUMP BALANCE PLUG AS FOLLOWS. PUMP 10 SBLS CHEM  
 WASH, 302  
 SACS OR 62 BBLS OF 15.8# G-NEAT CMT @1.15 YIELD, CMT IN RETURNSAT  
 SURFACE. CMT  
 788 TO SURFACE  
 OPEN WELL TO TANK, FLOW CHECK 15 MIN. (WSEA 10-C). TOP OFF CMT. SWI  
 RIG DOWN. CLEAN RETURN TANK. PU ALL EQUIPMENT. MRO. FINAL REPORT.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

Reclamation - Storm Water - Pit						
<b>Storm Water:</b>						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass			Material Handling And Spill Prevention	Pass	
Comment: <input style="width: 90%;" type="text"/> Corrective Action: <input style="width: 90%;" type="text"/> <span style="float: right;">Date: _____</span>						
<b>Pits:</b> <input type="checkbox"/> NO SURFACE INDICATION OF PIT						

COGCC Comments		
Comment	User	Date
<p><b>CECMC Inspection Report Summary:</b></p> <p>On WED 12/06/2023 at approximately 09:30 hrs. I, Bret Evins, conducted an on-site inspection at:                      Operator Name: NOBLE ENERGY INC                      Location Name: HOWARD USX A-66N64W/9NWSE                      Location ID: 306349                      Well Name(s):                      Howard USX A 9-10.                      API:                      123-24495.                      Location County: Weld County, Colorado                      Weather: Mostly Sunny, damp from prior storm.</p> <p>While there, I observed:                      Well(s): 1: Plugged &amp; Abandoned   PA.                      Plugging Operations: Cementing; Courtesy squeeze.                      Battery: Active.                      Active Battery SE corner GPS coordinates: 40.496656 / -104.550730                      Well GPS coordinates: 40.498780 / -104.552830</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	12/08/2023

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707602164	Site photo(s)	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6350971">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6350971</a>