



WPU-36-1-H2 pad looking south. Anchors are marked with 48" lathe with high visibility flagging and paint.



Stormwater ditch located along eastern edge of pad. No stormwater flow was noted during 11/03/2023 and 11/29/2023 inspection.



Sloping on the north and east areas of the pad were seeded and coconut matting was placed in areas of potential erosion.

