

# Inspection Photos

Loc: 321097

Operator: INVESTMENT EQUIPMENT LLC

Inspection Date: 12/6/2023

County: BACA



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing west at the former access road. The cattleguard has been removed.



## Inspection Photos



**Photo 2.** View of desirable vegetation beginning to establish along the road.



## Inspection Photos



**Photo 3.** Facing back east toward the road. There is tall undesirable weeds which will need to be controlled.



## Inspection Photos



**Photo 4.** Facing south along the former access road.



## Inspection Photos



**Photo 5.** Facing south toward the wellsite. It appears soils were decompacted along the road at the location.



## Inspection Photos



**Photo 6.** Facing south along the access road at the location. Soils were decompacted but desirable vegetation did not appear to be establishing, The dark brown vegetation is undesirable weeds that will need to be controlled..

